

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Cessna Aircraft Company	Category Airframe	Model 172S				Part #: 172S Serial #: 172S10754	
2004-15-18 9/12/2004	To prevent unintentionally engaging the KAP 140 autopilot computer system, which could cause the pilot to take,contd.	©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>
2005-05-53 R1 C 3/21/2005	To prevent loss of airplane control due to incorrect or inadequate rigging of critical flight systems	©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>
2005-13-10 8/9/2005	To replace any incorrect circuit breaker installed in the MC01-3A main electrical power junction box,contd.	©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>
2006-17-04 9/1/2006	Superseded by 2007-08-03	©ATP	Superseded by 2007-08-03	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>
2007-05-10 4/11/2007	To prevent the crew seat cylinder lock assembly from bending, cracking, or failing.	©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>
2007-08-03 5/2/2007	To detect & correct potential loss of fuel flow, which may result in partial or complete loss of engine power,contd.	©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. By
Manufacturer Cessna Aircraft Company	Category Airframe	Model 172S			Part #: 172S Serial #: 172S10754	
2008-02-18 2/28/2008 ©ATP	To prevent premature separation of the collar, which could result in the parachute failing to,contd. ©ATP	2/28/08 ©ATP	NA to aircraft. Parachute STC not installed	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins
2008-03-02 3/6/2008 ©ATP	To detect and correct chafing of the fuel return line assembly, which could result in fuel leaking under,contd. ©ATP	3/6/08 ©ATP	Superseded by 2012-02-02	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins
2008-05-09 4/8/2008 ©ATP	To prevent failure of the seat base/back attach brackets, which could result in the seats collapsing,contd. ©ATP	4/8/08 ©ATP	NA by aircraft serial number	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins
2008-10-02 5/12/2008 ©ATP	To prevent erroneous indications from the altimeter, airspeed, and vertical speed,contd. ©ATP	5/12/08 ©ATP	NA by aircraft serial number	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins
2008-26-10 1/5/2009 ©ATP	To prevent erroneous indications from the altimeter, airspeed, and vertical speed,contd. ©ATP	1/5/09 ©ATP	NA to aircraft. Delivered from the manufacturer after March 31, 2008, and no modification/ rework done.	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins
2008-26-10 C 1/5/2009 ©ATP	To prevent erroneous indications from the altimeter, airspeed, and vertical speed,contd. ©ATP	1/5/09 ©ATP	NA to aircraft. Delivered from the manufacturer after March 31, 2008, and no modification/ rework done.	Once ©ATP	NA Signature: <i>James S. Jenkins</i>	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, Iowa 52001
563-589-3812

Report Produced By: University of
Dubuque

Content Revision: 10/4/2013

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Cessna Aircraft Company	Category Airframe	Model 172S				Part #: 172S Serial #: 172S10754	
2011-06-02 5/26/2011 ©ATP	To prevent interruption of electrical power to the FADEC, which could result in an uncommanded engine,contd.	2022-2 ©ATP	NA to aircraft STC not installed	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
2011-06-02 C 5/26/2011 ©ATP	To prevent interruption of electrical power to the FADEC, which could result in an uncommanded engine,contd.	TACH ©ATP	NA to aircraft FADEC - STC not installed	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
2012-02-02 3/13/2012 ©ATP	To inspect the fuel return line assembly for chafing which could result in fuel leaking & fuel vapors,contd.		Complied paragraph (g)(2) complied w/SB 07-28-01 SEE #2 AF LOG, 7-10-12, tach 2446.0	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
2012-22-01 12/28/2012 ©ATP	To inspect the fuel return line assembly for chafing; replace the fuel return line assembly if chafing,contd.	12-22-2012 ©ATP	NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
2013-03-15 3/19/2013 ©ATP	To install the forward and aft fuel return line support clamps and brackets; inspect for a minimum clearance,contd.		NA by aircraft serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
2013-11-11 8/1/2013 ©ATP	To prevent failure of the engine oil pressure switch diaphragm, which results in loss of engine oil,contd.	SEE RECURRING AD LIST ©ATP	SEE RECURRING AD LIST	Recur ©ATP	SEE RECURRING AD LIST	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature: SEE RECURRING AD LIST

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, Iowa 52001
563-589-3812

Report Produced By: University of
Dubuque

Content Revision: 10/4/2013

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Cessna Aircraft Company	Category Airframe	Model 172S				Part #: 172S Serial #: 172S10754	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
9				Once		1. 2. 3. 4.	
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							
Signature:							

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A	
66-20-04 8/27/1966	TO PREVENT FURTHER FAILURES OF OIL FILTER ADAPTER GASKET, P/N 74904	©ATP	NA to engine. New config. gasket installed	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Serial #: L-34166-51E
73-23-01 R(4) 1/13/1977	TO PREVENT PISTON PIN FAILURES RESULTING FROM GRINDING CRACKS WHICH OCCURRED DURING MANUFACTURE	©ATP	NA to engine by serial number	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
75-08-09 R(3) 8/18/1977	TO PREVENT OIL PUMP FAILURES, INSPECT, REPLACE AND ASSEMBLE THE OIL PUMP DRIVE SHAFT AND DRIVE IMPELLER	©ATP	NA to engine by manufacture date	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
75-09-15 4/30/1975	TO PREVENT POSSIBLE FUEL STARVATION TO THE ENGINE	©ATP	NA to fuel injector by part number	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
78-23-10 11/7/1978	TO PREVENT AN IN-FLIGHT POWER LOSS DUE TO AN OVER RICH CONDITION, CONTD.	©ATP	NA to fuel injector by part number	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
79-04-05 9/26/1979	TO PREVENT AN IN-FLIGHT POWER LOSS DUE TO THE SEPARATION OF THE P/N 2529192 REGULATOR DIAPHRAGM STEM ASSEMBLY	©ATP	NA to fuel injector by part number	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A	
81-18-04 R2 6/7/1982	Superseded by 96-09-10	©ATP	Superseded by 96-09-10	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Serial #: L-34166-51E
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	
90-04-06 R1 5/28/1991	TO PREVENT OIL LINE FRACTURE AND LOSS OF ENGINE OIL	©ATP	NA engine - no propeller governor installed	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	
91-14-22 8/19/1991	Superseded by 2004-10-14	©ATP	Superseded by 2004-10-14	Recur	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	
92-12-05 7/10/1992	TO PREVENT PISTON PIN FAILURE, OR PISTON RELEASE, AND ENGINE FAILURE	©ATP	NA to engine model (-L2A)	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	
93-02-05 6/14/1993	Superseded by 2002-26-01	©ATP	Superseded by 2002-26-01	Recur	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	
96-09-10 C 7/15/1996	TO PREVENT OIL PUMP FAILURE DUE TO IMPELLER FAILURE, WHICH COULD RESULT IN AN ENGINE FAILURE	©ATP	PCW at OH. Steel impellers installed	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP		Signature: <i>James Jenkins</i>	

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. By
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A Serial #: L-34166-51E
96-23-03 12/17/1996 ©ATP	TO PREVENT AN INFLIGHT ENGINE FAILURE DUE TO FUEL STARVATION, WHICH COULD RESULT IN A FORCED LANDING ©ATP	24841	NA to engine. Engine shipped from Lycoming after August 14, 1996	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
97-01-03 1/21/1997 ©ATP	Superseded by 97-15-11 ©ATP	744	Superseded by 97-15-11	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
97-15-11 8/12/1997 ©ATP	TO PREVENT PISTON PIN FAILURE, WHICH COULD RESULT IN ENGINE FAILURE ©ATP		NA by engine model number.	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
98-02-08 3/30/1998 ©ATP	TO PREVENT CRANKSHAFT FAILURE, WHICH CAN RESULT IN ENGINE FAILURE, PROPELLER SEPARATION, FORCED LANDING, AND, CONTD. ©ATP	9-25-12	PCW at OH. SEE #2 ENG LOG, 5/12/2012	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
98-17-11 C 10/19/1998 ©ATP	TO PREVENT CRANKSHAFT FAILURE DUE TO CRACKING, WHICH COULD RESULT IN AN INFLIGHT ENGINE FAILURE AND POSSIBLE, CONTD. ©ATP		NA to engine by serial number and last OH date	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
98-18-12 9/28/1998 ©ATP	Superseded by 2003-14-03 ©ATP		Superseded by 2003-14-03	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. By
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A Serial #: L-34166-51E
2002-26-01 1/31/2003	Superseded by 2008-14-07 ©ATP	2008-1 ©ATP	Superseded by 2008-14-07	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2003-14-03 8/14/2003	To prevent rotary fuel pump leaks, which could result in an engine failure, engine fire, and damage to or,contd. ©ATP	2008-1 ©ATP	NA to engine diaphragm fuel pump installed. NOT rotary pump	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2004-10-14 C 6/25/2004	To prevent loosening or failure of the crankshaft gear retaining bolt, which may cause sudden engine failure ©ATP	2008-1 ©ATP	PCW by insp. at OH. "Gear mod P/C/W" SEE #2 ENG LOG, 5/12/2012	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2005-19-11 10/21/2005	To prevent failure of the crankshaft, which could result in total engine power loss, in-flight failure, and,contd. ©ATP	2008-1 ©ATP	NA to engine by model	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2006-06-16 4/27/2006	To prevent failure of the crankshaft, which could result in total engine power loss, in-flight engine,contd. ©ATP	2008-1 ©ATP	NA to engine by model and serial number	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2006-10-21 C2 6/22/2006	To prevent fatigue failure of the connecting rod & possible uncommanded shutdown of the engine ©ATP	2008-1 ©ATP	NA to engine. NO - ECI parts installed	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>

©ATP

Printed 9/25/2012 12:59:26PM

Page 4 of 9

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A	
2006-12-07 7/11/2006	To prevent loss of engine power due to cracks in the cylinder assemblies & possible engine failure caused,contd.	©ATP	2006-12-07 7/11/2006 NA to engine. NO - ECi parts installed	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
2006-20-09 11/3/2006	To prevent failure of the crankshaft, which will result in total engine power loss, in-flight engine,contd.	©ATP	2006-20-09 11/3/2006 NA by engine model number (-L2A) *SUPERSEDED BY 2012-12-01*	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
2007-04-19 R1 5/7/2007	To prevent cylinder separation that can lead to engine failure, possible engine compartment fire, and,contd.	©ATP	2007-04-19 R1 5/7/2007 NA to engine. NO - Superior Air Parts, Inc. (SAP), cylinder assemblies installed	Once	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
2008-06-51 E 3/12/2008	Superseded by 2008-08-14	©ATP	2008-06-51 E 3/12/2008 Superseded by 2008-08-14	Recur	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
2008-08-14 4/29/2008	Superseded by 2009-02-03	©ATP	2008-08-14 4/29/2008 Superseded by 2009-02-03	Recur	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
2008-14-07 8/14/2008	To prevent failure of the fuel injector fuel lines that would allow fuel to spray into the engine compartment,contd.	©ATP	2008-14-07 8/14/2008 Superseded by 2011-26-04	Recur	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	
©ATP	©ATP			©ATP	Signature:		
©ATP							

FAA Airworthiness Directive Compliance Record

Content Revision: 5/20/2016 File ID: N6196P						Report Produced By: University of Dubuque		
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By	
Manufacturer Lycoming	Category Engine	Model IO-360-L2A				Part #: IO-360-L2A Serial #: L-34166-51E		
2008-19-05 10/20/2008	To prevent loss of engine power due to cracks at the head-to-barrel interface in the cylinder assemblies,contd.	©ATP	Superseded by 2009-26-12	Recur	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	
2009-02-03 2/9/2009	To prevent a lean running engine, which could result in a substantial loss of engine power and subsequent,contd.	©ATP	NA to fuel servo. Has a letter "G" on the fuel injection servo plug	Recur	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	
2009-26-12 2/4/2010	To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure,contd.	©ATP	NA as per para (c). NO - ECi parts installed	Recur	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	
2011-15-10 8/16/2011	To correct an AFS fuel servo diaphragm	©ATP	Superseded by 2012-03-06	Once	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	
2011-26-04 1/25/2012	To prevent failure of the fuel injector fuel lines that would allow fuel to spray into the engine compartment,contd.	©ATP	Superseded by 2015-19-07	Recur	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	
2012-03-06 C 2/24/2012	To prevent an in-flight engine shutdown due to a failed fuel servo diaphragm, and damage to the airplane	©ATP	NA to fuel servo by serial number IAW AVStar AFS-SB6 and Lycoming SB-596	Once	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins	Signature: <i>James S. Jenkins</i>	

FAA Airworthiness Directive Compliance Record

	2000 University Ave. Dubuque, Iowa 52001 563-589-3812					Report Produced By: University of Dubuque										
Content Revision: 5/20/2016		File ID: N6196P		Aircraft Registration: N6196P												
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By									
Manufacturer Lycoming		Category Engine		Model IO-360-L2A												
2012-03-07 3/27/2012 ©ATP	To prevent engine in-flight shutdown, power loss, and reduced control of the airplane ©ATP	TACM 3-27-16	NA HA-6 carberuator NOT installed	Once ©ATP	NA	Part #: IO-360-L2A Serial #: L-34166-51E		1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>								
						Signature: <i>James S. Jenkins</i>										
2012-19-01 10/24/2012 ©ATP	To prevent failure of the crankshaft, which will result in total engine power loss, in-flight engine,contd. ©ATP	5-24-16	NA by engine model	Once ©ATP	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins		1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>								
						Signature: <i>James S. Jenkins</i>										
2015-02-07 3/11/2015 ©ATP	To prevent the propeller governor shaft set screw from coming loose, causing damage to the engine and,contd. ©ATP		NA engine not equipped with a front-mounted propeller governor	Once ©ATP	NA	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins		1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>								
						Signature: <i>James S. Jenkins</i>										
2015-19-07 11/3/2015 ©ATP	To prevent failure of the fuel injector fuel lines, which could lead to uncontrolled engine fire, engine,contd. ©ATP	SEE RECURRING AD LIST	SEE RECURRING AD LIST	Recur ©ATP	SEE RECURRING AD LIST	1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins		1. University of Dubuque 2.AP 3.3015266 4. James S. Jenkins Signature: SEE RECURRING AD LIST								
						Signature: SEE RECURRING AD LIST										
9				Once		1. 2. 3. 4.		Signature: Signature:								
						Signature: Signature:										
©ATP																
Printed 5/24/2016 8:55:53AM					Page 7 of 9											

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type 3. Cert. Num. 4. Author. By
Precision Airmotive Manufacturer	Category Fuel Injected System	Model RSA-5AD1				Part #: Serial #:
73-10-02 5/16/1973 ©ATP	TO DETECT DEFECTIVE DIAPHRAGM ASSEMBLIES ©ATP	7/8/11	In compliance with paragraph (a)	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
79-21-08 10/24/1979 ©ATP	TO PREVENT A FUEL FLOW CUTOFF TO THE ENGINE AND SUBSEQUENT LOSS OF POWER ©ATP	7/24/11	NA to fuel injector by PN	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
79-26-03 12/26/1979 ©ATP	REGULATOR STEM AND LOCK ©ATP		NA to fuel injector by PN	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2008-06-51 E 3/12/2008 ©ATP	Superseded by 2008-08-14 ©ATP		Superseded by 2008-08-14	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2008-08-14 4/29/2008 ©ATP	Superseded by 2009-02-03 ©ATP	7-25-11	Superseded by 2009-02-03	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
2009-02-03 2/9/2009 ©ATP	To prevent a lean running engine, which could result in a substantial loss of engine power and subsequent, contd. ©ATP		NA to fuel servo. Has a letter "G" on the fuel injection servo plug	Recur ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>
						©ATP

FAA Airworthiness Directive Compliance Record



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Precision Airmotive	Category Fuel Injected System	Model RSA-5AD1				Part #: Serial #:	
2012-03-06 C 2/24/2012 ©ATP	To prevent an in-flight engine shutdown due to a failed fuel servo diaphragm, and damage to the airplane	9-25-12 TACH 2484.1 ©ATP	NA to fuel servo by serial number IAW AVStar AFS-SB6 and Lycoming SB-596	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
Manufacturer Textron Lycoming	Category Fuel Pumps	Model LW15473				Part #: Serial #:	
92-20-07 L 10/5/1992 ©ATP	Superseded by 93-05-21	©ATP	Superseded by 93-05-21	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
93-05-21 L 3/25/1993 ©ATP	Superseded by 93-11-11	©ATP	Superseded by 93-11-11	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:
93-11-11 6/21/1993 ©ATP	TO PREVENT DISRUPTION OF FUEL FLOW TO THE ENGINE, WHICH CAN RESULT IN A LOSS OF ENGINE POWER	©ATP	NA to fuel pump - pump installed after November 24, 1992	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins	Signature:

PROPELLER & ACCESSORIES

FAA Airworthiness Directive Compliance Record

N6196P



2000 University Ave. Dubuque, IA 52004
563-589-3812

Report Produced By: James Jenkins

Content Revision: 9/24/2012

File ID: N6196P

Aircraft Registration: N6196P

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 2. Cert. Type	3. Cert. Num. 4. Author. By
Manufacturer Induction Air Filters	Category Air Filter	Model PAPER INDUCTION AIRFILTER				Part #: Serial #:	
84-26-02 1/29/1985	TO PREVENT POSSIBLE ENGINE POWER LOSS OR STOPPAGE CAUSED BY ENGINE INGESTION OF FRAGMENTS, CONTD.	SEE RECURRING AD LIST 5-15-13 2756.1 ©ATP	SEE RECURRING AD LIST (NA to PN of synthetic air filter installed (AD NA to synthetic air filters)) ©ATP	Recur ©ATP	SEE RECURRING AD LIST NA ©ATP	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: SEE RECURRING AD LIST	
Manufacturer ACS Products Company	Category Ignition Switches	Model IGNITION SWITCHES				Part #: <i>James S. Jenkins</i> Serial #:	
93-05-06 4/29/1993	TO PREVENT FAILURE OF IGNITION SWITCHES	SEE RECURRING AD LIST ©ATP	SEE RECURRING AD LIST ©ATP	Recur ©ATP	SEE RECURRING AD LIST ©ATP	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: SEE RECURRING AD LIST	
Manufacturer Garmin International	Category Transponder	Model GTX 33				Part #: Serial #: 891	
2005-01-19 2/23/2005	To prevent interrogating aircraft from possibly receiving inaccurate replies, due to suppression, contd.	9-25-12 TACH 24B4.1 ©ATP	PCW at time of airworthiness. Current software version 5.00	Once ©ATP	NA	1. University of Dubuque 2. AP 3. 3015266 4. James S. Jenkins Signature: <i>James S. Jenkins</i>	