

# University of Dubuque 2013-2016 Fire Drill Report

## 2016 Fire Drills Spring Term

| Date of Drill | Case Number | Time of Drill | Hall Name                                | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|--|-------------|--|--|
| 05/02/2016    | 16-05-0168  | 1530 to 1547  | Aitchison Hall<br>(701 Auburn Street)    |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (48) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.   |
| 05/02/2016    | 16-05-0168  | 1550 to 1605  | Cassat Hall<br>(2200 Bennett Street)     |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (46) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
| 05/05/2016    | 16-05-0173  | 1855 to 1912  | Chlapaty Hall<br>(80 Dodge Street)       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)                     | All (52) evacuated within the two minutes. All (126) fire safety devices, and (59) illuminated signs performed as anticipated.   |
| 05/02/2016    | 16-05-0168  | 1610 to 1617  | Donnell Hall<br>(2250 Bennett Street)    |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (37) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
| 05/02/2016    | 16-05-0168  | 1725 to 1740  | Park Village 2455<br>(2455 Dodge Street) |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (7) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.  |
| 05/02/2016    | 16-05-0168  | 1705 to 1720  | Park Village 2465<br>(2465 Dodge Street) |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (11) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 05/02/2016    | 16-05-0168  | 1745 to 1810  | Park Village 2475<br>(2475 Dodge Street) |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (16) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |

|            |            |              |                                       |  |  |  |
|------------|------------|--------------|---------------------------------------|--|--|--|
| 05/05/2016 | 16-05-0173 | 1605 to 1617 | Park Village 2525 (2525 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (12) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
| 05/05/2016 | 16-05-0173 | 1625 to 1641 | Park Village 2535 (2535 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (21) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
| 05/05/2016 | 16-05-0173 | 1644 to 1658 | Park Village 2545 (2545 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (13) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
|            |            |              | Potterveld A () (Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |
|            |            |              | Potterveld B () (Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |
|            |            |              | Potterveld C () (Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                              | Day of Week | Description of Fire Safety System | Brief Summary   |
|---------------|-------------|---------------|---|-------------|-----------------------------------|---|
|               |             |               | Airport- Americas Hanger (Dubuque Regional Airport) |             | smoke detector, fire extinguisher | All () evacuated within the two minutes. All () fire safety devices, and (5) illuminated signs performed as anticipated.  |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)     |             | fire extinguisher                 | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated.  |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport) |             | smoke detector, fire extinguisher | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated.  |
|               |             |               | Alumni Hall (1131 N. Algona St.)                    |             | fire extinguishers                | No fire drill was conducted. Building is only open when having service. All () evacuated within the two minutes. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed. |

|            |            |              |  |       |  |  |
|------------|------------|--------------|--|-------|--|--|
| 04/14/2016 | 16-04-0134 | 1138 to 1141 | Blades Hall<br>(1171 N. Algona St.)                          | Thur. | fire alarm panel, smoke detector, horns, fire extinguisher   | All (85) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.   |
|            |            |              | Cedar Rapids Campus<br>(294 Blairs Ferry Rd NE)              |       | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher  | All () evacuated within the two minutes. All (13) fire safety devices, and (6) illuminated signs performed as anticipated.   |
| 04/14/2016 | 16-04-0134 | 1358 to 1401 | Chlapaty Wellness Center<br>(150 McCormick Street Extension) | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (45) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (6) strobes, and (2) speakers failed to function   |
|            |            |              | Daycare Center<br>(1001 McCormick St.)                       |       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | All () evacuated within the two minutes. All (8) fire safety devices, and (3) illuminated signs performed as anticipated.  |
| 04/14/2016 | 16-04-0134 | 1129 to 1133 | Dunlap Technology Building<br>(1250 McCormick St.)           | Thur. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All (64) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 04/14/2016 | 16-04-0134 | 1331 to 1337 | Goldthorp Science Hall<br>(1150 N. Algona St.)               | Thur. | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water                               | All (58) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.  |
|            |            |              | Heating Plant<br>(755 Auburn Street)                         |       | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. All () evacuated within the two minutes. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. |
| 04/14/2016 | 16-04-0134 | 1422 to 1430 | Heritage Center<br>(2255 Bennett Street)                     | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (75) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated. (1) fire safety device failed to function   |
| 04/14/2016 | 16-04-0134 | 1124 to 1126 | Hub<br>(1025 N. Algona Street)                               | Thur. | fire extinguishers   | All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.   |
|            |            |              | Maintenance Bldg.<br>(125 McCormick Street Extension)        |       | fire extinguishers   | No fire drill was conducted. All () evacuated within the two minutes. This building has no fire safety devices. All (5) illuminated signs worked as anticipated.   |
| 04/14/2016 | 16-04-0134 | 1112 to 1117 | McCormick/Stoltz Gym<br>(1250 McCormick St.)                 | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (35) evacuated within the two minutes. All (40) fire safety devices, and (38) illuminated signs performed as anticipated. (1) strobe failed to function.   |

|            |            |              |  |       |   |  |
|------------|------------|--------------|--|-------|---|--|
| 04/14/2016 | 16-04-0134 | 1409 to 1411 | Mercer/Birmingham Hall<br>(205 McCormick Street Extension)                       | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (50) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.   |
| 04/14/2016 | 16-04-0134 | 1157 to 1201 | Myers Building MTAC<br>(455 North Algona)  | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (115) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated. (1) illuminated sign failed to work.  |
| 04/14/2016 | 16-04-0134 | 1059 to 1104 | Myers Library<br>(2105 Grace Street)   | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (176) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.    |
| 04/14/2016 | 16-04-0134 | 1343 to 1346 | Peters Commons<br>(1100 N. Algona St.)   | Thur. | fire alarm panel, strobe lights, horns, fire extinguishers  | All (58) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.  |
| 04/14/2016 | 16-04-0134 | 1148 to 1151 | Severance Hall<br>(1000 N. Algona St.)   | Thur. | fire alarm panel, strobe lights, horns, fire extinguishers  | All (52) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area. |
| 04/14/2016 | 16-04-0134 | 1048 to 1051 | Smith Hall<br>(2205 Grace Street)  | Thur. | horns, fire extinguishers   | All (12) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.   |
| 04/14/2016 | 16-04-0134 | 1123 to 1125 | Van Vliet Hall<br>(1025 N. Algona St.)   | Thur. | Fire alarm panel, horns, fire extinguishers   | All (31) evacuated within the two minutes. All (3) fire safety devices, and (9) illuminated signs performed as anticipated.  |
|            |            |              | Veteran's Memorial Training Center<br>(90 McCormick Str.)<br>Opened (01/15/2014) |       | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All ( ) evacuated within the two minutes. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.  |

### 2016 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name                             | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---------------------------------------|-------------|--|---|
|               |             |               | Aitchison Hall<br>(701 Auburn Street) |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | All ( ) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated. |

|  |  |  |  |   |  |
|--|--|--|--|---|--|
|  |  |  | Cassat Hall<br>(2200 Bennett Street)     | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors  | All () evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
|  |  |  | Chlapaty Hall<br>(80 Dodge Street)       | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All () evacuated within the two minutes. All (126) fire safety devices, and (59) illuminated signs performed as anticipated.   |
|  |  |  | Donnell Hall<br>(2250 Bennett Street)    | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors  | All () evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
|  |  |  | Park Village 2455<br>(2455 Dodge Street) | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All () evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
|  |  |  | Park Village 2465<br>(2465 Dodge Street) | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All () evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
|  |  |  | Park Village 2475<br>(2475 Dodge Street) | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All () evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
|  |  |  | Park Village 2525<br>(2525 Dodge Street) | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All () evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.   |
|  |  |  | Park Village 2535<br>(2535 Dodge Street) | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All () evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.   |

|  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
|  |  |  | Park Village 2545<br>(2545 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All () evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
|  |  |  | Potterveld A ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |
|  |  |  | Potterveld B ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |
|  |  |  | Potterveld C ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                       | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|--|-------------|--|---|
|               |             |               | Airport- Americas Hanger<br>(Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | All () evacuated within the two minutes. All () fire safety devices, and (5) illuminated signs performed as anticipated.  |
|               |             |               | Airport- Iowa Hanger<br>(Dubuque Regional Airport)           |             | fire extinguisher  | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated.  |
|               |             |               | Airport- Operations Bldg<br>(Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated.  |
|               |             |               | Alumni Hall<br>(1131 N. Algona St.)                          |             | fire extinguishers   | No fire drill was conducted. Building is only open when having service. All () evacuated within the two minutes. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed. |
|               |             |               | Blades Hall<br>(1171 N. Algona St.)                          |             | fire alarm panel, smoke detector, horns, fire extinguisher   | All () evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.  |
|               |             |               | Cedar Rapids Campus<br>(294 Blairs Ferry Rd NE)              |             | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher  | All () evacuated within the two minutes. All (13) fire safety devices, and (6) illuminated signs performed as anticipated.  |
|               |             |               | Chlapaty Wellness Center<br>(150 McCormick Street Extension) |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All () evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated.   |
|               |             |               | Daycare Center<br>(1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | All () evacuated within the two minutes. All (8) fire safety devices, and (3) illuminated signs performed as anticipated.   |

|  |  |  |  |   |  |
|--|--|--|--|---|--|
|  |  |  | Dunlap Technology Building<br>(1250 McCormick St.)         | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkler system(water)   | All () evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
|  |  |  | Goldthorp Science Hall<br>(1150 N. Algona St.)             | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water  | All () evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.  |
|  |  |  | Heating Plant<br>(755 Auburn Street)                       | fire extinguishers  | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. All () evacuated within the two minutes. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. |
|  |  |  | Heritage Center<br>(2255 Bennett Street)                   | fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All () evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated.   |
|  |  |  | Hub<br>(1025 N. Algona Street)                             | fire extinguishers  | Staff can not hear the alarm inside their area. All () evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.  |
|  |  |  | Maintenance Bldg.<br>(125 McCormick Street Extension)      | fire extinguishers  | No fire drill was conducted. All () evacuated within the two minutes. This building has no fire safety devices. All (5) illuminated signs worked as anticipated.   |
|  |  |  | McCormick/Stoltz Gym<br>(1050 McCormick St.)               | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)                                      | All () evacuated within the two minutes. All (41) fire safety devices, and (38) illuminated signs performed as anticipated.  |
|  |  |  | Mercer/Birmingham Hall<br>(205 McCormick Street Extension) | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All () evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.   |
|  |  |  | Myers Building MTAC<br>(455 North Algona)                  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All () evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated.  |
|  |  |  | Myers Library<br>(2105 Grace Street)                       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All () evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.                         |

|  |  |  |   |  |   |   |
|--|--|--|---|--|---|---|
|  |  |  | Peters Commons<br>(1100 N. Algona St.)  |  | fire alarm panel, strobe lights, horns, fire extinguishers  | All ( ) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.  |
|  |  |  | Severance Hall<br>(1000 N. Algona St.)  |  | fire alarm panel, strobe lights, horns, fire extinguishers  | All ( ) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area. |
|  |  |  | Smith Hall<br>(2205 Grace Street)   |  | horns, fire extinguishers   | All ( ) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.   |
|  |  |  | Van Vliet Hall<br>(1025 N. Algona St.)  |  | Fire alarm panel, horns, fire extinguishers   | All ( ) evacuated within the two minutes. All (3) fire safety devices, and (9) illuminated signs performed as anticipated.  |
|  |  |  | Veteran's Memorial Training Center Practice Field House<br>(90 McCormick Street)<br>Opened (01/15/2014) |  | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All ( ) evacuated within the two minutes. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.   |

### 2015 Fire Drills Spring Term

| Date of Drill | Case Number | Time of Drill | Hall Name                             | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|---------------------------------------|-------------|--|--|
| 04/07/2015    | 15-04-0124  | 1917 to 1944  | Aitchison Hall<br>(701 Auburn Street) | Tues.       | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors                                       | All (39) evacuated within the two minutes. All (129) fire safety devices, and (12) illuminated signs performed as anticipated. (1) fire safety devices (interior sounders) failed to function correctly. |
| 04/27/2015    | 15-04-0161  | 2045 to 2120  | Cassat Hall<br>(2200 Bennett Street)  | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors                                       | All (56) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
| 05/04/2015    | 15-05-0172  | 1859 to 1912  | Chlapaty Hall<br>(80 Dodge Street)    | Mon.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All (42) evacuated within the two minutes. All (175) fire safety devices, and (57) illuminated signs performed as anticipated.   |
| 04/27/2015    | 15-04-0161  | 2137 to 2145  | Donnell Hall<br>(2250 Bennett Street) | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors                                       | All (45) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |

|            |            |              |                                       |       |  |  |
|------------|------------|--------------|---------------------------------------|-------|--|--|
| 05/05/2015 | 15-05-0175 | 1850 to 1902 | Park Village 2455 (2455 Dodge Street) | Tues. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (7) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.  |
| 05/05/2015 | 15-05-0175 | 1850 to 1900 | Park Village 2465 (2465 Dodge Street) | Tues. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (18) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 05/05/2015 | 15-05-0172 | 1935 to 1947 | Park Village 2475 (2475 Dodge Street) | Mon.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (32) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 05/05/2015 | 15-05-0175 | 1909 to 1913 | Park Village 2525 (2525 Dodge Street) | Tues. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (7) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |
| 05/05/2015 | 15-05-0175 | 1914 to 1920 | Park Village 2535 (2535 Dodge Street) | Tues. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (10) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.   |
| 05/05/2015 | 15-05-0175 | 1921 to 1928 | Park Village 2545 (2545 Dodge Street) | Tues. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (5) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |
|            |            |              | Potterveld A () (Demolished 06/06/13) |       | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.   |
|            |            |              | Potterveld B () (Demolished 06/06/13) |       | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.   |

|  |  |  |                 |  |   |   |
|--|--|--|-----------------|--|---|---|
|  |  |  | Potterveld C () |  | smoke detector, fire extinguisher, fire doors | No fire drill was conducted. Building was |
|--|--|--|-----------------|--|---|---|

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|---|-------------|--|--|
|               |             |               | Airport- Americas Hanger (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.   |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher  | No fire drill was conducted.   |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.   |
|               |             |               | Alumni Hall (1131 N. Algona St.)                          |             | fire extinguishers   | No fire drill was conducted. Building is only open when having service.  |
| 03/20/2015    | 15-03-0103  | 1325 to 1330  | Blades Hall (1171 N. Algona St.)                          | Fri.        | fire alarm panel, smoke detector, horns, fire extinguisher   | All (4) evacuated within the two minutes. All (8) fire safety devices, and (8) illuminated signs performed as anticipated.   |
|               |             |               | Cedar Rapids Campus (294 Blairs Ferry Rd NE)              |             | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher  | No fire drill was conducted. Building has (13) fire safety devices, and (6) illuminated signs.   |
| 05/04/2015    | 15-05-0173  | 1423 to 1429  | Chlapaty Wellness Center (150 McCormick Street Extension) | Mon.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (67) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (7) strobes failed to perform as required. |
|               |             |               | Daycare Center (1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | No fire drill was conducted by security staff only done by Daycare staff.  |
| 05/06/2015    | 15-05-0179  | 1315 to 1319  | Dunlap Technology Building (1250 McCormick St.)           | Tue.        | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All (51) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 05/06/2015    | 15-05-0179  | 1303 to 1307  | Goldthorp Science Hall (1150 N. Algona St.)               | Tue.        | fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system-water                       | All (146) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.   |
|               |             |               | Heating Plant (755 Auburn Street)                         |             | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.  |
| 03/20/2015    | 15-03-0103  | 1354 to 1359  | Heritage Center (2255 Bennett Street)                     | Fri.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (29) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated.   |

|            |            |              |  |      |  |  |
|------------|------------|--------------|--|------|--|--|
|            |            |              | Hub<br>(1025 N. Algona Street)                             |      | fire extinguishers   | No fire drill was conducted. Staff can not hear the alarm inside their area.   |
|            |            |              | Maintenance Bldg.<br>(125 McCormick Street Extension)      |      | fire extinguishers   | No fire drill was conducted.   |
| 03/20/2015 | 15-03-0103 | 1310 to 1320 | McCormick/Stoltz Gym<br>(1250 McCormick St.)               | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (5) evacuated within the two minutes. All (33) fire safety devices, and (36) illuminated signs performed as anticipated. (1) fire safety devices (exterior horn/strobe) failed to function correctly.              |
| 05/04/2015 | 15-05-0173 | 1417 to 1419 | Mercer/Birmingham Hall<br>(205 McCormick Street Extension) | Mon. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (17) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.   |
| 03/20/2015 | 15-03-0103 | 1412 to 1420 | Myers Building MTAC<br>(455 North Algona)                  | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (23) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated. (1) fire safety device (exterior horn/strobe) failed to function correctly.              |
| 05/06/2015 | 15-05-0179 | 1325 to 1337 | Myers Library<br>(2105 Grace Street)                       | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (137) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.    |
| 03/20/2015 | 15-03-0103 | 1340 to 1347 | Peters Commons<br>(1100 N. Algona St.)                     | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (8) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the Snack Bar area.  |
| 03/20/2015 | 15-03-0103 | 1300 to 1305 | Severance Hall<br>(1000 N. Algona St.)                     | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (15) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area. |
| 03/20/2015 | 15-03-0103 | 1246 to 1249 | Smith Hall<br>(2205 Grace Street)                          | Fri. | horns, fire extinguishers  | All (3) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.  |
| 03/20/2015 | 15-03-0103 | 1253 to 1257 | Van Vliet Hall<br>(1025 N. Algona St.)                     | Fri. | Fire alarm panel, horns, fire extinguishers  | All (4) evacuated within the two minutes. All (3) fire safety devices, and (8) illuminated signs performed as anticipated.   |

|            |            |              |   |      |   |   |
|------------|------------|--------------|---|------|---|---|
| 03/20/2015 | 15-03-0103 | 1105 to 1115 | Veteran's Memorial Training Center (90 McCormick Str.)<br>Opened (01/15/2014) | Fri. | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | No one was inside the building. All (26) fire safety devices, and (3) illuminated signs performed as anticipated. (1) fire safety device (exterior horn/strobe) failed to function correctly. |
|------------|------------|--------------|---|------|---|---|

### 2015 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name                             | Day of Week | Description of Fire Safety System   | Brief Summary  |
|---------------|-------------|---------------|---------------------------------------|-------------|---|--|
| 10/05/2015    | 15-10-0307  | 1935 to 1943  | Aitchison Hall (701 Auburn Street)    | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors  | All (60) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.   |
| 10/05/2015    | 15-10-0307  | 2009 to 2016  | Cassat Hall (2200 Bennett Street)     | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors  | All (47) evacuated within 3.5 minutes(not an acceptable time of two minutes), one student refused to leave. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.   |
| 10/20/2015    | 15-10-0339  | 1859 to 1912  | Chlapaty Hall (80 Dodge Street)       | Tue.        | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All (74) evacuated within 3.5 minutes(not an acceptable time of two minutes). All (126) fire safety devices, and (59) illuminated signs performed as anticipated.  |
| 10/05/2015    | 15-10-0307  | 1955 to 2003  | Donnell Hall (2250 Bennett Street)    | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors  | All (68) evacuated within three minutes(not an acceptable time of two minutes). All (25) fire safety devices, and (10) illuminated signs performed as anticipated.   |
| 10/20/2015    | 15-10-0339  | 1925 to 1936  | Park Village 2455 (2455 Dodge Street) | Tue.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All (11) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 10/20/2015    | 15-10-0339  | 1937 to 1943  | Park Village 2465 (2465 Dodge Street) | Tue.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)        | All (13) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |

|            |            |              |                                       |      |  |  |
|------------|------------|--------------|---------------------------------------|------|--|--|
| 10/20/2015 | 15-10-0339 | 1937 to 1943 | Park Village 2475 (2475 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (16) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 10/20/2015 | 15-10-0339 | 1608 to 1617 | Park Village 2525 (2525 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (8) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |
| 10/20/2015 | 15-10-0339 | 1625 to 1632 | Park Village 2535 (2535 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (14) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.   |
| 10/20/2015 | 15-10-0339 | 1634 to 1638 | Park Village 2545 (2545 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (3) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |
|            |            |              | Potterveld A () (Demolished 06/06/13) |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.   |
|            |            |              | Potterveld B () (Demolished 06/06/13) |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.   |
|            |            |              | Potterveld C ()                       |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                              | Day of Week | Description of Fire Safety System | Brief Summary  |
|---------------|-------------|---------------|---|-------------|-----------------------------------|--|
|               |             |               | Airport- Americas Hanger (Dubuque Regional Airport) |             | smoke detector, fire extinguisher | All () evacuated within the two minutes. All () fire safety devices, and (5) illuminated signs performed as anticipated. |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)     |             | fire extinguisher                 | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated. |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport) |             | smoke detector, fire extinguisher | All () evacuated within the two minutes. All () fire safety devices, and (4) illuminated signs performed as anticipated. |

|            |            |              |  |       |   |  |
|------------|------------|--------------|--|-------|---|--|
|            |            |              | Alumni Hall<br>(1131 N. Algona St.)                          |       | fire extinguishers  | No fire drill was conducted. Building is only open when having service. All ( ) evacuated within the two minutes. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed. |
| 10/06/2015 | 15-10-0315 | 1418 to 1420 | Blades Hall<br>(1171 N. Algona St.)                          |       | fire alarm panel, smoke detector, horns, fire extinguisher  | All (45) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.   |
|            |            |              | Cedar Rapids Campus<br>(294 Blairs Ferry Rd NE)              |       | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher   | No fire drill was conducted. Building has (13) fire safety devices, and (6) illuminated signs.   |
| 10/07/2015 | 15-10-0315 | 1418 to 1430 | Chlapaty Wellness Center<br>(150 McCormick Street Extension) | Wed   | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All (95) evacuated within the two minutes. All (73) fire safety devices, and (17) illuminated signs performed as anticipated. (8) strobe lights failed to function correctly.  |
|            |            |              | Daycare Center<br>(1001 McCormick St.)                       |       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher   | All ( ) evacuated within the two minutes. All (8) fire safety devices, and (3) illuminated signs performed as anticipated. No fire drill was conducted by security staff only done by Daycare staff.   |
| 10/06/2015 | 15-10-0315 | 1426 to 1431 | Dunlap Technology Building<br>(1250 McCormick St.)           |       | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkler system(water)   | All (55) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 10/06/2015 | 15-10-0315 | 1334 to 1339 | Goldthorp Science Hall<br>(1150 N. Algona St.)               | Tue.  | fire alarm panel,battery back-up,smoke detector,heat detector,strobe lights,horns,fire extinguisher,fire door,sprinkler system-water  | All (107) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.   |
|            |            |              | Heating Plant<br>(755 Auburn Street)                         |       | fire extinguishers  | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.  |
| 10/08/2015 | 15-10-0315 | 1425 to 1431 | Heritage Center<br>(2255 Bennett Street)                     | Thur. | fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (84) evacuated within the two minutes. All (101) fire safety devices, and (49) illuminated signs performed as anticipated. (1) safety device failed to function correctly.   |
| 10/06/2015 | 15-10-0315 | 1409 1413    | Hub<br>(1025 N. Algona Street)                               | Tue.  | fire extinguishers  | Staff can not hear the alarm inside their area. All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.   |
|            |            |              | Maintenance Bldg.<br>(125 McCormick Street Extension)        |       | fire extinguishers  | No fire drill was conducted. This building has no fire safety devices. Building has (5) illuminated signs.   |

|            |            |              |   |      |   |   |
|------------|------------|--------------|---|------|---|---|
| 10/06/2015 | 15-10-0315 | 1323 to 1326 | McCormick/Stoltz Gym<br>(1050 McCormick St.)  | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)                            | All (31) evacuated within the two minutes. All (33) fire safety devices, and (37) illuminated signs performed as anticipated.   |
| 10/07/2015 | 15-10-0315 | 1406 to 1408 | Mercer/Birmingham Hall<br>(205 McCormick Street Extension)  | Wed  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (88) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.  |
| 10/06/2015 | 15-10-0315 | 1439 to 1445 | Myers Building MTAC<br>(455 North Algona)   | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (97) evacuated within the two minutes. All (43) fire safety devices, and (22) illuminated signs performed as anticipated. (1) illuminated sign failed to function correctly.  |
| 10/06/2015 | 15-10-0315 | 1302 to 1308 | Myers Library<br>(2105 Grace Street)  | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                | All (140) evacuated within the two minutes. (33) fire safety devices, and (35) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area. (2) illuminated signs failed to function correctly. |
| 10/06/2015 | 15-10-0315 | 1350 to 1352 | Peters Commons<br>(1100 N. Algona St.)  | Tue. | fire alarm panel, strobe lights, horns, fire extinguishers  | All (28) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.   |
| 10/06/2015 | 15-10-0315 | 1400-1404    | Severance Hall<br>(1000 N. Algona St.)  | Tue. | fire alarm panel, strobe lights, horns, fire extinguishers  | All (40) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.  |
| 10/06/2015 | 15-10-0315 | 1255 to 1259 | Smith Hall<br>(2205 Grace Street)   | Tue. | horns, fire extinguishers   | All (14) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.  |
| 10/06/2015 | 15-10-0315 | 1409 to 1413 | Van Vliet Hall<br>(1025 N. Algona St.)  | Tue. | Fire alarm panel, horns, fire extinguishers   | All (20) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.  |
| 10/07/2015 | 15-10-0315 | 1434 to 1436 | Veteran's Memorial Training Center Practice Field House<br>(90 McCormick Street)<br>Opened (01/15/2014) | Wed  | fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | All (2) evacuated within the two minutes. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.   |

## 2014 Fire Drills Spring Term

| Date of Drill | Case Number | Time of Drill | Hall Name                                | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|--|-------------|--|--|
| 04/25/2014    | 14-04-0138  | 2002 to 2044  | Aitchison Hall<br>(701 Auburn Street)    | Fri.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (58) evacuated within the two minutes. All (135) fire safety devices, and (12) illuminated signs performed as anticipated. (1) sounder failed to function correctly.   |
| 04/25/2014    | 14-04-0138  | 2045 to 2120  | Cassat Hall<br>(2200 Bennett Street)     | Fri.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (71) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
| 04/25/2014    | 14-04-0138  | 2137 to 2145  | Donnell Hall<br>(2250 Bennett Street)    | Fri.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (58) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.  |
| 04/30/2014    | 14-04-0141  | 2100 to       | Park Village 2455                        | Wed.        | fire panel, battery back-up, monitor(external  | All (12) evacuated within the two minutes. All   |
| 04/30/2014    | 14-04-0141  | 2045 to 2052  | Park Village 2465<br>(2465 Dodge Street) | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (12) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 04/30/2014    | 14-04-0141  | 2030 to 2043  | Park Village 2475<br>(2475 Dodge Street) | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (25) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |
| 04/30/2014    | 14-04-0141  | 1955 to 2008  | Park Village 2525<br>(2525 Dodge Street) | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (16) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.   |
| 04/30/2014    | 14-04-0141  | 2012 to 2023  | Park Village 2535<br>(2535 Dodge Street) | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (9) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |

|            |            |              |                                       |      |  |   |
|------------|------------|--------------|---------------------------------------|------|--|---|
| 04/30/2014 | 14-04-0141 | 1900 to 1920 | Park Village 2545 (2545 Dodge Street) | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (9) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
|            |            |              | Potterveld A () (Demolished 06/06/13) |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.  |
|            |            |              | Potterveld B () (Demolished 06/06/13) |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.  |
|            |            |              | Potterveld C () (Demolished 06/06/13) |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was demolished 06/06/13.  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---|-------------|--|---|
|               |             |               | Airport- Americas Hanger (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Alumni Hall (1131 N. Algona St.)                          |             | fire extinguishers   | No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. One additional illuminated sign is needed.                        |
| 04/09/2014    | 14-04-0107  | 1342 to 1346  | Blades Hall (1171 N. Algona St.)                          | Wed.        | fire alarm panel, smoke detector, horns, fire extinguisher   | All (53) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.  |
|               |             |               | Cedar Rapids Campus (294 Blairs Ferry Road NE)            |             | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher  | No fire drill was conducted.  |
| 04/25/2014    | 14-04-0129  | 1148 to 1155  | Chlapaty Wellness Center (150 McCormick Street Extension) | Fri.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (23) evacuated within the two minutes. All (76) fire safety devices, and (16) illuminated signs performed as anticipated, (6) fire safety devices failed to function correctly. |
|               |             |               | Daycare Center (1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | No fire drill was conducted by security staff only done by Daycare staff.   |

|            |            |              |  |      |  |  |
|------------|------------|--------------|--|------|--|--|
| 04/09/2014 | 14-04-0107 | 1333 to 1335 | Dunlap Technology Building<br>(1250 McCormick St.)         | Wed. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkler system(water)  | All (49) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 04/25/2014 | 14-04-0129 | 1328 to 1332 | Goldthorp Science Hall<br>(1150 N. Algona St.)             | Fri. | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water                               | All (41) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.  |
|            |            |              | Heating Plant<br>(755 Auburn Street)                       |      | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.  |
|            |            |              | Heritage Center<br>(2255 Bennett Street)                   |      | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | No fire drill was conducted. This building has (102) fire safety devices, and (49) illuminated signs.  |
| 04/09/2014 | 14-04-0107 | 1414 to 1419 | Hub<br>(1025 N. Algona Street)                             | Wed. | fire extinguishers   | Staff can not hear the alarm inside their area. All (3) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.   |
|            |            |              | Maintenance Bldg.<br>(125 McCormick Street Extension)      |      | fire extinguishers   | No fire drill was conducted. This building has no fire safety devices.   |
| 04/09/2014 | 14-04-0107 | 1322 to 1327 | McCormick/Stoltz Gym<br>(1250 McCormick St.)               | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (18) evacuated within the two minutes. All (33) fire safety devices, and (37) illuminated signs performed as anticipated.  |
| 04/25/2014 | 14-04-0129 | 1140 to 1142 | Mercer/Birmingham Hall<br>(205 McCormick Street Extension) | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (45) evacuated within the two minutes. All (24) fire safety devices, and (7) illuminated signs performed as anticipated.   |
|            |            |              | Myers Building MTAC<br>(455 North Algona)                  |      | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | No fire drill was conducted. This building has (43) fire safety devices, and (30) illuminated signs.   |
| 04/25/2014 | 14-04-0129 | 1110 to 1118 | Myers Library<br>(2105 Grace Street)                       | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (69) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area. |
| 04/09/2014 | 14-04-0107 | 1357 to 1400 | Peters Commons<br>(1100 N. Algona St.)                     | Wed. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (21) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the Snack Bar area.   |

|            |            |              |  |      |  |  |
|------------|------------|--------------|--|------|--|--|
| 04/09/2014 | 14-04-0107 | 1405 to 1407 | Severance Hall<br>(1000 N. Algona St.)   | Wed. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (34) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area. |
| 04/09/2014 | 14-04-0107 | 1315 to 1318 | Smith Hall<br>(2205 Grace Street)  | Wed. | horns, fire extinguishers  | All (10) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.   |
| 04/09/2014 | 14-04-0107 | 1414 to 1419 | Van Vliet Hall<br>(1025 N. Algona St.)   | Wed. | Fire alarm panel, horns, fire extinguishers  | All (25) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.   |
| 04/25/2014 | 14-04-0129 | 1204 to 1210 | Veteran's Memorial Training Center<br>(90 McCormick Street)<br>Opened (01/15/2014) | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | Building was empty. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.  |

### 2014 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name   | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---|-------------|--|---|
| 12/11/2014    | 14-12-0360  | 2002 to 2020  | Aitchison Hall<br>(701 Auburn Street)                   | Thur.       | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (69) evacuated within the two minutes. Only (133) fire safety devices, and (12) illuminated signs performed as anticipated. Three sounders failed to work correctly   |
| 12/11/2014    | 14-12-0362  | 1940 to 1954  | Cassat Hall<br>(2200 Bennett Street)                    | Thur.       | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (83) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.   |
|               |             |               | Donnell Hall<br>(2250 Bennett Street)                   |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | No fire drill was conducted. This building has (25) fire safety devices, and (10) illuminated signs.  |
|               |             |               | Chlapaty Hall<br>(80 Dodge Street)<br>Opened (08/15/14) |             | fire panel, battery back-up, monitor(external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water) | No fire drill was conducted.  |
|               |             |               | Park Village 2455<br>(2455 Dodge Street)                |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. |

|  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
|  |  |  | Park Village 2465<br>(2465 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard.</u> |
|  |  |  | Park Village 2475<br>(2475 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard.</u> |
|  |  |  | Park Village 2525<br>(2525 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>   |
|  |  |  | Park Village 2535<br>(2535 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>   |
|  |  |  | Park Village 2545<br>(2545 Dodge Street) |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>   |
|  |  |  | Potterveld A ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was <u>demolished 06/06/13.</u>  |
|  |  |  | Potterveld B ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was <u>demolished 06/06/13.</u>  |
|  |  |  | Potterveld C ()<br>(Demolished 06/06/13) |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. Building was <u>demolished 06/06/13.</u>  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                 | Day of Week | Description of Fire Safety System | Brief Summary                |
|---------------|-------------|---------------|--|-------------|-----------------------------------|------------------------------|
|               |             |               | Airport- Americas Hanger<br>(Dubuque Regional Airport) |             | smoke detector, fire extinguisher | No fire drill was conducted. |
|               |             |               | Airport- Iowa Hanger<br>(Dubuque Regional Airport)     |             | fire extinguisher                 | No fire drill was conducted. |

|            |            |              |   |      |  |  |
|------------|------------|--------------|---|------|--|--|
|            |            |              | Airport- Operations Bldg (Dubuque Regional Airport)       |      | smoke detector, fire extinguisher  | No fire drill was conducted.   |
|            |            |              | Alumni Hall (1131 N. Algona St.)                          |      | fire extinguishers   | No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed. |
| 10/24/2014 | 14-10-0296 | 1401 to 1405 | Blades Hall (1171 N. Algona St.)                          |      | fire alarm panel, smoke detector, horns, fire extinguisher   | All (28) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.   |
|            |            |              | Cedar Rapids Campus (294 Blairs Ferry Road NE)            |      | fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher  | No fire drill was conducted.   |
| 10/30/2014 | 14-10-0309 | 1433 to 1438 | Chlapaty Wellness Center (150 McCormick Street Extension) | Thu. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                           | All (70) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs, 6 strobes malfunctioned.  |
|            |            |              | Daycare Center (1001 McCormick St.)                       |      | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher  | No fire drill was conducted by security staff only done by Daycare staff.  |
| 10/24/2014 | 14-10-0296 | 1411 to 1415 | Dunlap Technology Building (1250 McCormick St.)           | Fri. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All (72) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 10/24/2014 | 14-10-0296 | 1442 to 1450 | Goldthorp Science Hall (1150 N. Algona St.)               | Fri. | fire alarm panel,battery back-up,smoke detector,heat detector,strobe lights,horns,fire extinguisher,fire door,sprinkler system-water   | All (153) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.   |
|            |            |              | Heating Plant (755 Auburn Street)                         |      | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.  |
|            |            |              | Heritage Center (2255 Bennett Street)                     |      | fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system (water) | No fire drill was conducted. This building has (102) fire safety devices, and (49) illuminated signs.  |
|            |            |              | Hub (1025 N. Algona Street)                               |      | fire extinguishers   | No fire drill was conducted. Staff can not hear the alarm inside their area. This building has no fire safety devices. This building has (2) illuminated signs. One additional illuminated sign is needed.   |
|            |            |              | Maintenance Bldg. (125 McCormick Street Extension)        |      | fire extinguishers   | No fire drill was conducted. This building has no fire safety devices. Building has (5) illuminated signs.   |

|            |            |              |  |      |  |   |
|------------|------------|--------------|--|------|--|---|
| 10/30/2014 | 14-10-0309 | 1352 to 1357 | McCormick/Stoltz Gym<br>(1050 McCormick St.)                                       | Thu. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (18) evacuated within the two minutes. All (33) fire safety devices, and (36) illuminated signs performed as anticipated.   |
| 10/30/2014 | 14-10-0309 | 1443 to 1445 | Mercer/Birmingham Hall<br>(205 McCormick Street Extension)                         | Thu. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (29) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.  |
| 10/30/2014 | 14-10-0309 | 1418 to 1423 | Myers Building MTAC<br>(455 North Algona)  | Thu. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (186) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated.  |
| 10/30/2014 | 14-10-0309 | 1402-1407    | Myers Library<br>(2105 Grace Street)   | Thu. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (137) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm <u>inside their area.</u>    |
| 10/24/2014 | 14-10-0296 | 1356 to 1359 | Peters Commons<br>(1100 N. Algona St.)   | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (38) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the <u>Snack Bar area.</u>   |
| 10/24/2014 | 14-10-0296 | 1427 to 1432 | Severance Hall<br>(1000 N. Algona St.)   | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (54) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm <u>inside their area.</u> |
| 10/30/2014 | 14-10-0309 | 1345 to 1348 | Smith Hall<br>(2205 Grace Street)  | Thu. | horns, fire extinguishers  | All (23) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not <u>clearly hear the alarm.</u>   |
| 10/24/2014 | 14-10-0296 | 1419 to 1422 | Van Vliet Hall<br>(1025 N. Algona St.)   | Fri. | Fire alarm panel, horns, fire extinguishers  | All (32) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs <u>performed as anticipated.</u>   |
|            |            |              | Veteran's Memorial Training Center<br>(90 McCormick Street)<br>Opened (01/15/2014) |      | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | No fire drill was conducted. This building has (26) fire safety devices, and (3) illuminated signs.   |

### 2013 Fire Drills Spring Term

| Date of | Case | Time of | Hall Name | Day of | Description of Fire Safety System | Brief Summary |
|---------|------|---------|-----------|--------|-----------------------------------|---------------|
|---------|------|---------|-----------|--------|-----------------------------------|---------------|

| Drill      | Number     | Drill | Week                                     |      |  |   |
|------------|------------|-------|--|------|--|---|
| 05/01/2013 | 13-05-0185 | 1706  | Aitchison Hall<br>(701 Auburn Street)    | Wed. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (54) evacuated within the two minutes. All (136) fire safety devices performed as anticipated.  |
| 05/01/2013 | 13-05-0185 | 1729  | Cassat Hall<br>(2200 Bennett Street)     | Wed. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (28) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.   |
| 05/01/2013 | 13-05-0185 | 1740  | Donnell Hall<br>(2250 Bennett Street)    | Wed. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (36) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.   |
| 05/01/2013 | 13-05-0185 | 1808  | Park Village 2455<br>(2455 Dodge Street) | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (14) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard</u>   |
| 05/01/2013 | 13-05-0185 | 1817  | Park Village 2465<br>(2465 Dodge Street) | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (17) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard</u> . |
| 05/01/2013 | 13-05-0185 | 1834  | Park Village 2475<br>(2475 Dodge Street) | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (20) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard</u> . |
|            |            |       | Park Village 2525<br>(2525 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |       | Park Village 2535<br>(2535 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |       | Park Village 2545<br>(2545 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |       | Potterveld A                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |
|            |            |       | Potterveld B                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |
|            |            |       | Potterveld C                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System   | Brief Summary  |
|---------------|-------------|---------------|---|-------------|---|--|
|               |             |               | Airport- Americas Hanger (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher   | No fire drill was conducted.   |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher   | No fire drill was conducted.   |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher   | No fire drill was conducted.   |
|               |             |               | Alumni Hall (1131 N. Algona St.)                          |             | fire extinguishers  | No fire drill was conducted. Building is only open when having service.  |
| 04/29/2013    | 13-05-0185  | 1329          | Blades Hall (1171 N. Algona St.)                          | Tue.        | fire alarm panel, smoke detector, horns, fire extinguisher  | All (28) evacuated within the two minutes. All (8) fire safety devices performed as anticipated.   |
| 04/26/2013    | 13-04-0179  | 1305          | Chlapaty Wellness Center (150 McCormick Street Extension) | Fri.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All (26) evacuated within the two minutes. All (77 out of 81) fire safety devices performed as anticipated. (4) strobes failed to function as anticipated. |
|               |             |               | Daycare Center (1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher   | No fire drill was conducted.   |
| 04/26/2013    | 13-04-0179  | 1356          | Dunlap Technology Building (1250 McCormick St.)           | Fri.        | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)  | All (42) evacuated within the two minutes. All (9) fire safety devices performed as anticipated.   |
| 04/29/2013    | 13-05-0185  | 1340          | Goldthorp Science Hall (1150 N. Algona St.)               | Tue.        | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water  | All (111) evacuated within the two minutes. All (60) fire safety devices performed as anticipated.   |
|               |             |               | Heating Plant (755 Auburn Street)                         |             | fire extinguishers  | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.  |
|               |             |               | Heritage Center (2255 Bennett Street) (Open 04/10/2013)   |             | fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | No fire drill was conducted  |
| 04/26/2013    | 13-04-0179  | 1350          | Hub   | Fri.        | fire extinguishers  | Staff can not hear the alarm inside their area. All evacuated within the two minutes.  |
|               |             |               | Maintenance Bldg. (125 McCormick Street Extension)        |             | fire extinguishers  | No fire drill was conducted.   |

|            |            |      |   |      |  |   |
|------------|------------|------|---|------|--|---|
| 04/26/2013 | 13-04-0179 | 1328 | McCormick/Stoltz Gym<br>(1050 McCormick St.)            | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (17) evacuated within the two minutes. All (27) fire safety devices performed as anticipated.   |
| 04/26/2013 | 13-04-0179 | 1318 | Mercer/Birmingham Hall (205 McCormick Street Extension) | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors                          | All (15) evacuated within the two minutes. All (24) fire safety devices performed as anticipated.   |
| 04/26/2013 | 13-04-0179 | 1425 | Myers Building MTAC (455 North Algona)                  | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (52) evacuated within the two minutes. All (43) fire safety devices performed as anticipated.   |
| 04/26/2013 | 13-04-0179 | 1339 | Myers Library (2105 Grace Street)                       | Fri. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (92) evacuated within the two minutes. All (44) fire safety devices performed as anticipated. Staff of the Academic Success Center can not hear the alarm inside their area. Emergency exit door malfunctioned. |
| 04/26/2013 | 13-04-0179 | 1415 | Peters Commons (1100 N. Algona St.)                     | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (25) evacuated within the two minutes. All (6) fire safety devices performed as anticipated. No horns inside the Snack Bar area.  |
| 04/26/2013 | 13-04-0179 | 1405 | Severance Hall (1000 N. Algona St.)                     | Fri. | fire alarm panel, strobe lights, horns, fire extinguishers   | All (18) evacuated within the two minutes. All (10) fire safety devices performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.                          |
| 04/26/2013 | 13-04-0179 | 1255 | Smith Hall  | Fri. | horns, fire extinguishers  | All (13) evacuated within the two minutes. All (3)  |
| 04/26/2013 | 13-04-0179 | 1350 | Van Vliet Hall (1025 N. Algona St.)                     | Fri. | Fire alarm panel, horns, fire extinguishers  | All (9) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.   |

### 2013 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name                          | Day of Week | Description of Fire Safety System  | Brief Summary                |
|---------------|-------------|---------------|------------------------------------|-------------|--|------------------------------|
|               |             |               | Aitchison Hall (701 Auburn Street) |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | No fire drill was conducted. |
|               |             |               | Cassat Hall (2200 Bennett Street)  |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | No fire drill was conducted. |
|               |             |               | Donnell Hall (2250 Bennett Street) |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | No fire drill was conducted. |

|            |            |      |  |      |  |  |
|------------|------------|------|--|------|--|--|
|            |            |      | Park Village 2455<br>(2455 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.   |
|            |            |      | Park Village 2465<br>(2465 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.   |
|            |            |      | Park Village 2475<br>(2475 Dodge Street) |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.   |
| 11/19/2013 | 13-11-0403 | 1730 | Park Village 2525<br>(2525 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (25) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
| 11/19/2013 | 13-11-0403 | 1755 | Park Village 2535<br>(2535 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (28) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. |
| 11/19/2013 | 13-11-0403 | 1840 | Park Village 2545<br>(2545 Dodge Street) | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (8) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.  |
|            |            |      | Potterveld A                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.<br>Building demolished 05/15/2013   |
|            |            |      | Potterveld B                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |
|            |            |      | Potterveld C                             |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.<br>Building demolished 05/15/2013   |

| Date of Drill | Case Number | Time of Drill | Academic Building Name | Day of Week | Description of Fire Safety System | Brief Summary |
|---------------|-------------|---------------|------------------------|-------------|-----------------------------------|---------------|
|---------------|-------------|---------------|------------------------|-------------|-----------------------------------|---------------|

|            |            |           |  |       |   |  |
|------------|------------|-----------|--|-------|---|--|
|            |            |           | Airport- America Hanger<br>(Dubuque Regional<br>Airport)           |       | smoke detector, fire extinguisher   | No fire drill was conducted.   |
|            |            |           | Airport- Iowa Hanger<br>(Dubuque Regional<br>Airport)              |       | fire extinguisher   | No fire drill was conducted.   |
|            |            |           | Airport- Operations<br>Bldg (Dubuque<br>Regional Airport)          |       | smoke detector, fire extinguisher   | No fire drill was conducted.   |
|            |            |           | Alumni Hall<br>(1131 N. Algona St.)                                |       | fire extinguishers  | No fire drill was conducted. Building is only open when having service. This building has no fire safety devices.  |
| 10/03/2013 | 13-10-0323 | 1427-1431 | Blades Hall<br>(1171 N. Algona St.)                                | Thur. | fire alarm panel, smoke detector, horns, fire extinguisher  | All (45) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.   |
| 10/09/2013 | 13-10-0347 | 1419-1424 | Chlapaty Wellness<br>Center<br>(150 McCormick Street<br>Extension) | Wed.  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)                          | All (23) evacuated within the two minutes. All (76 out of 81) fire safety devices, and (16) illuminated signs performed as anticipated. (5) Fire safety devices failed to function as anticipated. |
|            |            |           | Daycare Center<br>(1001 McCormick St.)                             |       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher   | No fire drill was conducted.   |
| 10/03/2013 | 13-10-0323 | 1435-1439 | Dunlap Technology<br>Building<br>(1250 McCormick St.)              | Thur. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)  | All (16) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.   |
| 10/14/2013 | 13-10-0347 | 1329-1335 | Goldthorp Science Hall<br>(1150 N. Algona St.)                     | Mon.  | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water  | All (200) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.   |
|            |            |           | Heating Plant<br>(755 Auburn Street)                               |       | fire extinguishers  | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.  |
| 10/14/2013 | 13-10-0347 | 1415-1423 | Heritage Center<br>(2255 Bennett Street)<br>(Open 04/10/2013)      | Mon.  | fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (68) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated.   |
|            |            |           | Hub  |       | fire extinguishers  | No fire drill was conducted. Staff can not hear the alarm inside their area. This building has no fire safety devices.   |
|            |            |           | Maintenance Bldg.<br>(125 McCormick Street<br>Extension)           |       | fire extinguishers  | No fire drill was conducted. This building has no fire safety devices.   |

|            |            |           |   |       |  |   |
|------------|------------|-----------|---|-------|--|---|
| 10/03/2013 | 13-10-0323 | 1407-1413 | McCormick/Stoltz Gym<br>(1050 McCormick St.)            | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (14) evacuated within the two minutes. All (27) fire safety devices, and (16) illuminated signs performed as anticipated (2) signs malfunctioned.   |
| 10/09/2013 | 13-10-0347 | 1432-1437 | Mercer/Birmingham Hall (205 McCormick Street Extension) | Wed.  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors                          | All (49) evacuated within the two minutes. All (24) fire safety devices, and (7) illuminated signs performed as anticipated.  |
| 10/09/2013 | 13-10-0347 | 1351-1357 | Myers Building MTAC (455 North Algona)                  | Wed.  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (180) evacuated within the two minutes. All (43) fire safety devices, and (30) illuminated signs performed as anticipated.  |
| 10/03/2013 | 13-10-0323 | 1350-1358 | Myers Library (2105 Grace Street)                       | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (126) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center can not hear the alarm inside their area.                       |
| 10/14/2013 | 13-10-0347 | 1345-1400 | Peters Commons (1100 N. Algona St.)                     | Mon.  | fire alarm panel, strobe lights, horns, fire extinguishers   | All (25) evacuated within the two minutes. All (6) fire safety devices, and (10 out of 12) illuminated signs performed as anticipated. (2) illuminated signs failed to function as anticipated. No horns inside the Snack Bar area. |
| 10/09/2013 | 13-10-0347 | 1405-1409 | Severance Hall (1000 N. Algona St.)                     | Wed.  | fire alarm panel, strobe lights, horns, fire extinguishers   | All (40) evacuated within the two minutes. All (10) fire safety devices, and (18) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.              |
| 10/03/2013 | 13-10-0323 | 1340-1343 | Smith Hall (2205 Grace Street)                          | Thur. | horns, fire extinguishers  | All (20) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.  |
| 10/03/2013 | 13-10-0323 | 1419-1424 | Van Vliet Hall (1025 N. Algona St.)                     | Thur. | Fire alarm panel, horns, fire extinguishers  | All (18) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.  |

### 2012 Fire Drills Spring Term

| Date of Drill | Case Number | Time of Drill | Hall Name | Day of Week | Description of Fire Safety System | Brief Summary |
|---------------|-------------|---------------|-----------|-------------|-----------------------------------|---------------|
|---------------|-------------|---------------|-----------|-------------|-----------------------------------|---------------|

|            |            |      |                   |       |  |  |
|------------|------------|------|-------------------|-------|--|--|
| 04/25/2012 | 12-04-0163 | 1850 | Aitchison Hall    | Wed.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.  |
| 04/25/2012 | 12-04-0163 | 1825 | Cassat Hall       | Wed.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.  |
| 04/18/2012 | 12-04-0148 | 1846 | Donnell Hall      | Wed.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.  |
| 04/11/2012 | 12-04-0135 | 1830 | Park Village 2455 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated <u>within the two minutes.</u> |
| 04/11/2012 | 12-04-0135 | 1815 | Park Village 2465 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated <u>within the two minutes.</u> |
| 04/11/2012 | 12-04-0135 | 1800 | Park Village 2475 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated <u>within the two minutes.</u> |
| 04/09/2012 | 12-04-0132 | 1800 | Park Village 2525 | Mon.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. <u>All evacuated within the two minutes.</u>                            |
| 04/09/2012 | 12-04-0132 | 1815 | Park Village 2535 | Mon.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. <u>All evacuated within the two minutes.</u>                            |
| 04/09/2012 | 12-04-0132 | 1830 | Park Village 2545 | Mon.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. <u>All evacuated within the two minutes.</u>                            |
|            |            |      | Potterveld A      |       | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |
|            |            |      | Potterveld B      |       | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |
|            |            |      | Potterveld C      |       | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |

| Date of Drill | Case Number | Time of Drill | Academic Building Name | Day of Week | Description of Fire Safety System | Brief Summary |
|---------------|-------------|---------------|------------------------|-------------|-----------------------------------|---------------|
|---------------|-------------|---------------|------------------------|-------------|-----------------------------------|---------------|

|            |            |      |  |       |   |   |
|------------|------------|------|--|-------|---|---|
|            |            |      | Airport- America Hanger<br>(Dubuque Regional<br>Airport)           |       | smoke detector, fire extinguisher   | No fire drill was conducted.  |
|            |            |      | Airport- Iowa Hanger<br>(Dubuque Regional<br>Airport)              |       | fire extinguisher   | No fire drill was conducted.  |
|            |            |      | Airport- Operations<br>Bldg (Dubuque<br>Regional Airport)          |       | smoke detector, fire extinguisher   | No fire drill was conducted.  |
|            |            |      | Alumni Hall<br>(1131 N. Algona St.)                                |       | fire extinguishers  | No fire drill was conducted. Building is only open<br>when having service.                                      |
| 04/11/2012 | 12-04-0134 | 1416 | Blades Hall<br>(1171 N. Algona St.)                                | Wed.  | fire alarm panel, smoke detector, horns, fire<br>extinguisher   | All evacuated within the two minutes.   |
| 04/12/2012 | 12-04-0136 | 1131 | Chlapaty Wellness<br>Center<br>(150 McCormick Street<br>Extension) | Thur. | fire alarm panel, battery back-up, monitor<br>internally, smoke detector, heat detector, strobe<br>lights, horns, fire extinguisher, fire doors, sprinkler<br>system(water) | The strobes did not activate outside the wall<br>behind the bleachers. All evacuated within the two<br>minutes. |
|            |            |      | Daycare Center<br>(1001 McCormick St.)                             |       | fire alarm panel, battery back-up, monitor<br>internally, smoke detector, heat detector, strobe<br>lights, horns, fire extinguisher   | No fire drill was conducted.  |
| 04/11/2012 | 12-04-0134 | 1354 | Dunlap Technology<br>Building<br>(1250 McCormick St.)              | Wed.  | fire alarm panel, battery back-up, strobe lights,<br>horns, fire extinguisher, sprinkle system(water)   | All evacuated within the two minutes.   |
| 04/12/2012 | 12-04-0136 | 1051 | Goldthorp Science Hall<br>(1150 N. Algona St.)                     | Thur. | fire alarm panel,battery back-up,smoke<br>detector,heat detector,stroke lights,horns,fire<br>extinguisher,fire door,sprinkler system-water                                  | All evacuated within the two minutes.   |
|            |            |      | Heating Plant<br>(755 Auburn Street)                               |       | fire extinguishers  | No fire drill was conducted. Building is only<br>staffed when maintenance work is being done on<br>systems.     |
| 04/12/2012 | 12-04-0136 | 1035 | Hub  | Thur. | fire extinguishers  | Staff can not hear the alarm inside their area. All<br>evacuated within the two minutes.                        |
|            |            |      | Maintenance Bldg.<br>(125 McCormick Street<br>Extension)           |       | fire extinguishers  | No fire drill was conducted.  |
| 04/11/2012 | 12-04-0134 | 1404 | McCormick/Stoltz<br>Gym<br>(1050 McCormick St.)                    | Wed.  | fire alarm panel, battery back-up, monitor<br>internally, smoke detector, heat detector, strobe<br>lights, horns, fire extinguisher, sprinkler<br>system(water)             | All evacuated within the two minutes.   |
| 04/12/2012 | 12-04-0136 | 1140 | Mercer/Birmingham<br>Hall (205 McCormick<br>Street Extension)      | Thur. | fire alarm panel, battery back-up, monitor<br>internally, smoke detector, heat detector, strobe<br>lights, horns, fire extinguisher, fire doors                             | All evacuated within the two minutes.   |

|            |            |      |   |       |  |  |
|------------|------------|------|---|-------|--|--|
| 04/12/2012 | 12-04-0136 | 1118 | Myers Building MTAC<br>(455 North Algona) | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All evacuated within the two minutes.  |
| 04/12/2012 | 12-04-0136 | 1035 | Myers Library<br>(2105 Grace Street)      | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | Staff of the ASC complained that they could not hear the alarm inside their area. All evacuated within the two minutes.                  |
| 04/12/2012 | 12-04-0136 | 1404 | Peters Commons<br>(1100 N. Algona St.)    | Thur. | fire alarm panel, strobe lights, horns, fire extinguishers   | No horns inside the Snack Bar area. All evacuated within the two minutes.  |
| 04/12/2012 | 12-04-0136 | 1105 | Severance Hall<br>(1000 N. Algona St.)    | Thur. | fire alarm panel, strobe lights, horns, fire extinguishers   | The students in the back classrooms (101-102) and lounge can not hear the alarm inside their area. All evacuated within the two minutes. |
| 04/11/2012 | 12-04-0134 | 1335 | Smith Hall<br>(2205 Grace Street)         | Wed.  | horns, fire extinguishers  | Room 200 could not clearly hear the alarm. All evacuated within the two minutes.   |
| 04/11/2012 | 12-04-0134 | 1347 | Van Vliet Hall<br>(1025 N. Algona St.)    | Wed.  | Fire alarm panel, horns, fire extinguishers  | All evacuated within the two minutes.  |

### 2012 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name         | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|-------------------|-------------|--|--|
| 10/24/2012    | 12-10-0410  | 1519 to 1527  | Aitchison Hall    | Wed.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (95) evacuated within the two minutes. All (136) fire safety devices performed as anticipated.   |
| 10/24/2012    | 12-10-0410  | 1519 to 1527  | Cassat Hall       | Wed.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (56) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.  |
| 10/24/2012    | 12-10-0410  | 1552 to 1600  | Donnell Hall      | Wed.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All (73) evacuated within the two minutes, (2) students failed to evacuate within the appropriate time. All (25) fire safety devices performed as anticipated. |
| 10/24/2012    | 12-10-0410  | 1635 to 1640  | Park Village 2455 | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (17) evacuated within the two minutes. All (14) fire safety devices performed as anticipated.  |
| 10/24/2012    | 12-10-0410  | 1624 to 1629  | Park Village 2465 | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (22) evacuated within the two minutes. All (14) fire safety devices performed as anticipated.  |

|            |            |              |                   |      |  |   |
|------------|------------|--------------|-------------------|------|--|---|
| 10/24/2012 | 12-10-0410 | 1642 to 1648 | Park Village 2475 | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All (12) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. |
|            |            |              | Park Village 2525 |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |              | Park Village 2535 |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |              | Park Village 2545 |      | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|            |            |              | Potterveld A      |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |
|            |            |              | Potterveld B      |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |
|            |            |              | Potterveld C      |      | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.  |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---|-------------|--|---|
|               |             |               | Airport- America Hanger (Dubuque Regional Airport)        |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Alumni Hall (1131 N. Algona St.)                          |             | fire extinguishers   | No fire drill was conducted. Building is only open when having service.   |
| 10/04/2012    | 12-10-0369  | 1422 to 1425  | Blades Hall (1171 N. Algona St.)                          | Wed.        | fire alarm panel, smoke detector, horns, fire extinguisher   | All (18) evacuated within the two minutes. All (8) fire safety devices performed as anticipated.                                    |
| 10/04/2012    | 12-10-0369  | 1334 to 1342  | Chlapaty Wellness Center (150 McCormick Street Extension) | Wed.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (33) evacuated within the two minutes. Strobes (9) failed to work. All (71) other fire safety devices performed as anticipated. |
|               |             |               | Daycare Center (1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | No fire drill was conducted.  |

|            |            |              |   |      |  |  |
|------------|------------|--------------|---|------|--|--|
| 10/04/2012 | 12-10-0369 | 1429 to 1432 | Dunlap Technology Building<br>(1250 McCormick St.)      | Wed. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All (54) evacuated within the two minutes. All (9) fire safety devices performed as anticipated.   |
| 10/16/2012 | 12-10-0396 | 1428 to 1435 | Goldthorp Science Hall<br>(1150 N. Algona St.)          | Tue. | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water                               | All (154) evacuated within the two minutes. All (60) fire safety devices performed as anticipated.   |
|            |            |              | Heating Plant<br>(755 Auburn Street)                    |      | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.  |
|            |            |              | Hub   |      | fire extinguishers   | Staff can not hear the alarm inside their area. No fire drill was conducted.   |
|            |            |              | Maintenance Bldg.<br>(125 McCormick Street Extension)   |      | fire extinguishers   | No fire drill was conducted.   |
| 10/16/2012 | 12-10-0396 | 1440 to 1447 | McCormick/Stoltz Gym<br>(1050 McCormick St.)            | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All (19) evacuated within the two minutes, (1) person failed to evacuate within the appropriate time. All (27) fire safety devices performed as anticipated.   |
| 10/16/2012 | 12-10-0396 | 1415 to 1419 | Mercer/Birmingham Hall (205 McCormick Street Extension) | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors                          | All (57) evacuated within the two minutes. All (24) fire safety devices performed as anticipated.  |
| 10/16/2012 | 12-10-0396 | 1340 to 1351 | Myers Building MTAC<br>(455 North Algona)               | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All (96) evacuated within the two minutes. All (43) fire safety devices performed as anticipated.  |
| 10/16/2012 | 12-10-0396 | 1355 to 1401 | Myers Library<br>(2105 Grace Street)                    | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | Staff of the ASC could not hear the alarm inside their area. All (100) evacuated within the two minutes. All (44) fire safety devices performed as anticipated.                                      |
|            |            |              | Peters Commons<br>(1100 N. Algona St.)                  |      | fire alarm panel, strobe lights, horns, fire extinguishers   | No horns inside the Snack Bar area. All () evacuated within the two minutes. All () fire safety devices performed as anticipated.  |
| 10/04/2012 | 12-10-0369 | 1440 to 1445 | Severance Hall<br>(1000 N. Algona St.)                  | Wed. | fire alarm panel, strobe lights, horns, fire extinguishers   | The students in the back classrooms (101-102) and lounge can not hear the alarm inside their area. All (32) evacuated within the two minutes. All (10) fire safety devices performed as anticipated. |
| 10/04/2012 | 12-10-0369 | 1401 to 1404 | Smith Hall<br>(2205 Grace Street)                       | Wed. | horns, fire extinguishers  | Room 200 could not clearly hear the alarm. All (15) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.  |
| 10/04/2012 | 12-10-0369 | 1408 to 1412 | Van Vliet Hall<br>(1025 N. Algona St.)                  | Wed. | Fire alarm panel, horns, fire extinguishers  | All (32) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.   |

## 2011 Fire Drills Spring Term

| Date of Drill | Case Number | Time of Drill | Hall Name         | Day of Week | Description of Fire Safety System  | Brief Summary  |
|---------------|-------------|---------------|-------------------|-------------|--|--|
| 02/28/2011    | 11-02-0260  | 1822          | Aitchison Hall    | Mon.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | The following sounders malfunction (Rm. 213, 215). All evacuated within the two minutes. |
|               |             |               | Cassat Hall       |             | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | No fire drill was conducted.   |
| 02/17/2011    | 11-02-0185  | 1829          | Donnell Hall      | Tue.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.  |
|               |             |               | Park Village 2455 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.   |
|               |             |               | Park Village 2465 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.   |
| 03/01/2011    | 11-03-0262  | 1839          | Park Village 2475 | Tue.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.  |
|               |             |               | Park Village 2525 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.   |
|               |             |               | Park Village 2535 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.   |
|               |             |               | Park Village 2545 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.   |
|               |             |               | Potterveld A      |             | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |
|               |             |               | Potterveld B      |             | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted.   |

|  |  |  |              |  |   |                              |
|--|--|--|--------------|--|---|------------------------------|
|  |  |  | Potterveld C |  | smoke detector, fire extinguisher, fire doors | No fire drill was conducted. |
|--|--|--|--------------|--|---|------------------------------|

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---|-------------|--|---|
|               |             |               | Airport- America Hanger (Dubuque Regional Airport)        |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Alumni Hall (1131 N. Algona St.)                          | N/A         | fire extinguishers   | No fire drill was conducted. Building is only open when having service.                               |
| 02/17/2011    | 11-02-0184  | 1123          | Blades Hall (1171 N. Algona St.)                          | Thur.       | fire alarm panel, smoke detector, horns, fire extinguisher   | All evacuated within the two minutes.   |
| 02/23/2011    | 11-02-0220  | 1027          | Chlapaty Wellness Center (150 McCormick Street Extension) | Wed.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All evacuated within the two minutes.   |
| 02/23/2011    | 11-02-0220  | 1100          | Daycare Center (1001 McCormick St.)                       | Wed.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | All evacuated within the two minutes.   |
| 02/17/2011    | 11-02-0184  | 1115          | Dunlap Technology Building (1250 McCormick St.)           | Thur.       | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All evacuated within the two minutes.   |
| 02/23/2011    | 11-02-0220  | 1414          | Goldthorp Science Hall (1150 N. Algona St.)               | Wed.        | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water                               | All evacuated within the two minutes.   |
|               |             |               | Heating Plant (755 Auburn Street)                         | N/A         | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. |
|               |             |               | Hub   |             | fire extinguishers   | No fire drill was conducted.  |
|               |             |               | Maintenance Bldg. (125 McCormick Street Extension)        |             | fire extinguishers   | No fire drill was conducted.  |
| 02/17/2011    | 11-02-0184  | 1106          | McCormick/Stoltz Gym (1050 McCormick St.)                 | Thur.       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All evacuated within the two minutes.   |

|            |            |      |   |       |  |  |
|------------|------------|------|---|-------|--|--|
|            |            |      | Mercer/Birmingham Hall (205 McCormick Street Extension) |       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors                          | No fire drill was conducted. Building is currently under construction. |
|            |            |      | Myers Building MTAC (455 North Algona)                  |       | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | No fire drill was conducted.   |
| 02/17/2011 | 11-02-0184 | 1342 | Myers Library (2105 Grace Street)                       | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All evacuated within the two minutes.                                  |
|            |            |      | Peters Commons  |       |  | No fire drill was conducted.   |
| 02/23/2011 | 11-02-0220 | 1012 | Severance Hall (1000 N. Algona St.)                     | Wed.  | fire alarm panel, strobe lights, horns, fire extinguishers   | All evacuated within the two minutes.                                  |
| 02/17/2011 | 11-02-0184 | 1054 | Smith Hall (2205 Grace Street)                          | Thur. | horns, fire extinguishers  | All evacuated within the two minutes.                                  |
| 02/17/2011 | 11-02-0184 | 1134 | Van Vliet Hall (1025 N. Algona St.)                     | Thur. | Fire alarm panel, horns, fire extinguishers  | All evacuated within the two minutes.                                  |

### 2011 Fire Drills Fall Term

| Date of Drill | Case Number | Time of Drill | Hall Name         | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|-------------------|-------------|--|---|
| 09/28/2011    | 11-09-0783  | 1830          | Aitchison Hall    | Wed.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | Two pull station covers, and two sounders failed to function. All evacuated within the two minutes. |
| 09/29/2011    | 11-09-0785  | 1831          | Cassat Hall       | Thur.       | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | Pull station cover (2nd floor east side) did not function. All evacuated within the two minutes.    |
| 09/29/2011    | 11-09-0785  | 1842          | Donnell Hall      | Thur.       | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.   |
|               |             |               | Park Village 2455 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |
|               |             |               | Park Village 2465 |             | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted.  |

|  |  |  |                   |  |  |                              |
|--|--|--|-------------------|--|--|------------------------------|
|  |  |  | Park Village 2475 |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. |
|  |  |  | Park Village 2525 |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. |
|  |  |  | Park Village 2535 |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. |
|  |  |  | Park Village 2545 |  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | No fire drill was conducted. |
|  |  |  | Potterveld A      |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. |
|  |  |  | Potterveld B      |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. |
|  |  |  | Potterveld C      |  | smoke detector, fire extinguisher, fire doors  | No fire drill was conducted. |

| Date of Drill | Case Number | Time of Drill | Academic Building Name                                    | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|---|-------------|--|---|
|               |             |               | Airport- America Hanger (Dubuque Regional Airport)        |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Iowa Hanger (Dubuque Regional Airport)           |             | fire extinguisher  | No fire drill was conducted.  |
|               |             |               | Airport- Operations Bldg (Dubuque Regional Airport)       |             | smoke detector, fire extinguisher  | No fire drill was conducted.  |
| N/A           | N/A         | N/A           | Alumni Hall (1131 N. Algona St.)                          | N/A         | fire extinguishers   | No fire drill was conducted. Building is only open when having service.       |
| 09/21/2011    | 11-09-0782  | 1219          | Blades Hall (1171 N. Algona St.)                          | Wed.        | fire alarm panel, smoke detector, horns, fire extinguisher   | All evacuated within the two minutes.   |
| 09/28/2011    | 11-09-0782  | 1145          | Chlapaty Wellness Center (150 McCormick Street Extension) | Wed.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | Exterior strobe light did not function. All evacuated within the two minutes. |
|               |             |               | Daycare Center (1001 McCormick St.)                       |             | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher                                      | No fire drill was conducted by security staff only by Daycare staff.          |

|            |            |      |   |      |  |   |
|------------|------------|------|---|------|--|---|
| 09/21/2011 | 11-09-0782 | 1301 | Dunlap Technology Building<br>(1250 McCormick St.)      | Wed. | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All evacuated within the two minutes.   |
| 09/28/2011 | 11-09-0782 | 1057 | Goldthorp Science Hall<br>(1150 N. Algona St.)          | Wed. | fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water                               | All evacuated within the two minutes.   |
| N/A        | N/A        | N/A  | Heating Plant<br>(755 Auburn Street)                    | N/A  | fire extinguishers   | No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.   |
| 09/21/2011 | 11-09-0782 | 1208 | Hub   | Wed. | fire extinguishers   | Staff could not hear the sounder. All evacuated within the two minutes.   |
|            |            |      | Maintenance Bldg.<br>(125 McCormick Street Extension)   |      | fire extinguishers   | No fire drill was conducted.  |
| 09/28/2011 | 11-09-0782 | 1111 | McCormick/Stoltz Gym<br>(1050 McCormick St.)            | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All evacuated within the two minutes.   |
| 09/28/2011 | 11-09-0782 | 1158 | Mercer/Birmingham Hall (205 McCormick Street Extension) | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors                          | All evacuated within the two minutes.   |
| 09/28/2011 | 11-09-0782 | 1126 | Myers Building MTAC<br>(455 North Algona)               | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | Staff of the ASC complained that they could not hear the alarm inside their area. All evacuated within the two minutes.   |
| 09/28/2011 | 11-09-0782 | 1326 | Myers Library<br>(2105 Grace Street)                    | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/28/2011 | 11-09-0782 | 1415 | Peters Commons<br>(1100 N. Algona St.)                  | Wed. | fire alarm panel, strobe lights, horns, fire extinguishers   | No horns inside the Snack Bar area. All evacuated within the two minutes.   |
| 09/21/2011 | 11-09-0782 | 1251 | Severance Hall<br>(1000 N. Algona St.)                  | Wed. | fire alarm panel, strobe lights, horns, fire extinguishers   | The students in the back classrooms and lounge area are not able to hear any of the alarm bells in the event of a fire emergency. All evacuated within the two minutes. |
| 09/21/2011 | 11-09-0782 | 1319 | Smith Hall<br>(2205 Grace Street)                       | Wed. | horns, fire extinguishers  | Room 200 could not clearly hear the alarm. All evacuated within the two minutes.  |
| 09/21/2011 | 11-09-0782 | 1208 | Van Vliet Hall<br>(1025 N. Algona St.)                  | Wed. | Fire alarm panel, horns, fire extinguishers  | All evacuated within the two minutes.   |

## 2010 Fire Drills

| Date of Drill | Case Number | Time of Drill | Hall Name                | Day of Week | Description of Fire Safety System  | Brief Summary   |
|---------------|-------------|---------------|--------------------------|-------------|--|---|
| 04/12/2010    | 10-04-0433  | 939           | Goldthorp Science Center | Mon.        | fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system(water)                              | All evacuated within the two minutes.   |
| 04/12/2010    | 10-04-0433  | 954           | Dunlap Technology        | Mon.        | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All evacuated within the two minutes.   |
| 04/12/2010    | 10-04-0433  | 1008          | McCormick/ Stoltz Gym    | Mon.        | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)                     | 1 Coach failed the evacuate. All others evacuated within the two minutes.   |
| 04/12/2010    | 10-04-0433  | 1022          | Smith Hall               | Mon.        | horns, fire extinguishers  | Room 200 could not clearly hear the alarm. All others evacuated within the two minutes.   |
| 04/12/2010    | 10-04-0433  | 1034          | Van Vliet Hall           | Mon.        | Fire alarm panel, horns, fire extinguishers  | All evacuated within the two minutes.   |
| 04/12/2010    | 10-04-0431  | 1946          | Park Village 2475        | Mon.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 04/13/2010    | 10-04-0438  | 1033          | Blades Hall              | Tue.        | fire alarm panel, smoke detector, horns, fire extinguisher   | All evacuated within the two minutes.   |
| 04/16/2010    | 10-04-0459  | 936           | Peters Commons           | Fri.        | fire alarm panel, strobe lights, horns, fire extinguishers   | All evacuated within the two minutes.   |
| 04/22/2010    | 10-04-0486  | 1815          | Park Village 2465        | Thur.       | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. Emergency lighting on the 3rd floor did not work. All evacuated within the two minutes. |
| 04/22/2010    | 10-04-0486  | 1823          | Park Village 2545        | Thur.       | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.  |
| 04/22/2010    | 10-04-0486  | 1823          | Park Village 2475        | Thur.       | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. Emergency lighting on the 3rd floor did not work. All evacuated within the two minutes. |

|            |            |      |                          |       |  |   |
|------------|------------|------|--------------------------|-------|--|---|
| 04/22/2010 | 10-04-0486 | 1834 | Park Village 2535        | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.  |
| 04/22/2010 | 10-04-0486 | 1845 | Park Village 2525        | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.  |
| 04/22/2010 | 10-04-0486 | 1845 | Park Village 2455        | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated within the two minutes. |
| 04/29/2010 | 10-04-0529 | 1143 | Severance Hall           | Thur. | fire alarm panel, strobe lights, horns, fire extinguishers   | The students in the back classrooms are not able to hear any of the alarm bells in the event of a fire emergency. All others evacuated within two minutes   |
| 04/29/2010 | 10-04-0529 | 1153 | Myers Building           | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)         | The strobe in the men's restroom on the 1st floor near the business office did not work. All evacuated within the two minutes.  |
| 04/29/2010 | 10-04-0529 | 1213 | Chlapaty Wellness Center | Thur. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)         | All evacuated within the two minutes.   |
| 04/29/2010 | 10-04-0533 | 1804 | Aitchison Hall           | Thur. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.   |
| 04/29/2010 | 10-04-0533 | 1831 | Donnell Hall             | Thur. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.   |
| 04/29/2010 | 10-04-0533 | 1844 | Cassat Hall              | Thur. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.   |
| 09/27/2010 | 10-09-1238 | 1810 | Cassat Hall              | Mon.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All evacuated within the two minutes.   |
| 09/27/2010 | 10-09-1238 | 1837 | Donnell Hall             | Mon.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (1) student failed to leave within two minutes. All other students evacuated within the two minutes.  |
| 09/28/2010 | 10-09-1246 | 1755 | Aitchison Hall           | Tue.  | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | Audible were not functioning in the following rooms: 111, 211 201 202 207. All evacuated within the two minutes.  |

|            |            |      |                   |       |  |   |
|------------|------------|------|-------------------|-------|--|---|
| 09/28/2010 | 10-09-1246 | 1828 | Park Village 2475 | Tue.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/28/2010 | 10-09-1246 | 1836 | Park Village 2465 | Tue.  | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/29/2010 | 10-09-1251 | 1747 | Potterveld A      | Wed.  | smoke detector, fire extinguisher, fire doors  | All evacuated within the two minutes.   |
| 09/29/2010 | 10-09-1251 | 1751 | Potterveld B      | Wed.  | smoke detector, fire extinguisher, fire doors  | All evacuated within the two minutes.   |
| 09/29/2010 | 10-09-1251 | 1815 | Potterveld C      | Wed.  | smoke detector, fire extinguisher, fire doors  | All evacuated within the two minutes.   |
| 09/30/2010 | 10-09-1255 | 1806 | Park Village 2455 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/30/2010 | 10-09-1255 | 1818 | Park Village 2545 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/30/2010 | 10-09-1255 | 1823 | Park Village 2535 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 09/30/2010 | 10-09-1255 | 1829 | Park Village 2525 | Thur. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All evacuated within the two minutes.   |
| 10/08/2010 | 10-10-1304 | 936  | Smith Hall        | Fri.  | horns, fire extinguishers  | All evacuated within the two minutes.   |
| 10/08/2010 | 10-10-1304 | 944  | Van Vliet Hall    | Fri.  | Fire alarm panel, horns, fire extinguishers  | All evacuated within the two minutes.   |
| 10/08/2010 | 10-10-1304 | 955  | Blades Hall       | Fri.  | fire alarm panel, smoke detector, horns, fire extinguisher   | All evacuated within the two minutes.   |
| 10/08/2010 | 10-10-1304 | 1005 | Severance Hall    | Fri.  | fire alarm panel, strobe lights, horns, fire extinguishers   | All evacuated within the two minutes.   |
| 10/19/2010 | 10-10-1354 | 1354 | Dunlap Technology | Tue.  | fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)   | All evacuated within the two minutes.   |
| 10/19/2010 | 10-10-1354 | 1404 | Myers Building    | Tue.  | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)         | (2) staff members failed to evacuate. All others evacuated within the two minutes. One strobe light did not work in the 1st floor men's room. |

|            |            |      |                          |      |  |   |
|------------|------------|------|--------------------------|------|--|---|
| 10/19/2010 | 10-10-1354 | 1418 | Chlapaty Wellness Center | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | One strobe light did not work in the 3rd floor North end, and one on the South side near the southern glass door. All evacuated within the two minutes. |
| 11/02/2010 | 10-11-1403 | 1409 | Goldthorp Science Center | Tue. | fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system(water)                      | All evacuated within the two minutes.   |
| 11/02/2010 | 10-11-1403 | 1422 | McCormick/ Stoltz Gym    | Tue. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)             | All evacuated within the two minutes.   |
| 11/02/2010 | 10-11-1403 | 1440 | Peters Commons           | Tue. | fire alarm panel, strobe lights, horns, fire extinguishers   | All evacuated within the two minutes.   |
| 11/03/2010 | 10-11-1406 | 1432 | Myers Library            | Wed. | fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water) | All evacuated within the two minutes.   |

### 2009 Fire Drills

| Date of Drill | Case Number | Time of Drill | Hall Name         | Day of Week | Description of Fire Safety System  | Brief Summary                                   |
|---------------|-------------|---------------|-------------------|-------------|--|---|
| 03/17/2009    | 09-03-0325  | 2100          | Cassat Hall       | Tue.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (1) student failed to leave within two minutes  |
| 03/17/2010    | 09-03-0325  | 2100          | Donnell Hall      | Tue.        | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 03/18/2009    | 09-03-0326  | 2000          | Park Village 2455 | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | (4) students failed to leave within two minutes |
| 03/18/2009    |             | 2130          | Park Village 2465 | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 03/18/2009    | 09-03-0326  | 2000          | Park Village 2475 | Wed.        | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | (2) students failed to leave within two minutes |

|            |            |      |                   |      |  |   |
|------------|------------|------|-------------------|------|--|---|
| 03/19/2009 |            | 2130 | Park Village 2525 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 03/19/2009 |            | 2130 | Park Village 2535 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 03/19/2009 |            | 2130 | Park Village 2545 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 10/12/2009 | 09-10-1039 | 1958 | Cassat Hall       | Mon. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (2) students failed to leave within two minutes |
| 10/12/2009 | 09-10-1039 | 1958 | Aitchison Hall    | Mon. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 10/13/2009 | 09-10-1048 | 1938 | Donnell Hall      | Tue. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (1) student failed to leave within two minutes  |
| 10/13/2009 | 09-10-1048 | 1948 | Park Village 2455 | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | (2) students failed to leave within two minutes |
| 10/13/2009 | 09-10-1048 | 1948 | Park Village 2475 | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | (2) students failed to leave within two minutes |

### 2008 Fire Drills

| Date of Drill | Case Number | Time of Drill | Hall Name    | Day of Week | Description of Fire Safety System  | Brief Summary                                  |
|---------------|-------------|---------------|--------------|-------------|--|--|
| 03/17/2008    | 09-03-0325  | 2100          | Cassat Hall  | Tue         | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | (1) student failed to leave within two minutes |
| 03/17/2008    | 09-03-0325  | 2100          | Donnell Hall | Tue         | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors | All students evacuated within two minutes      |

|            |            |      |                   |      |  |   |
|------------|------------|------|-------------------|------|--|---|
| 04/21/2008 | 08-04-0435 | 1953 | Cassat Hall       | Mon. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (2) students failed to leave within two minutes |
| 04/21/2008 | 08-04-0435 | 2012 | Aitchison Hall    | Mon. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 04/21/2008 | 08-04-0435 | 2034 | Donnell Hall      | Mon. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | (3) students failed to leave within two minutes |
| 04/22/2008 | 08-04-0443 | 2024 | Park Village 2465 | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 04/22/2008 | 08-04-0443 | 2024 | Park Village 2475 | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 04/22/2008 | 08-04-0443 | 2038 | Park Village 2455 | Tue. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 04/23/2008 |            | 2030 | Park Village 2525 | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 04/23/2008 |            | 2030 | Park Village 2535 | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 04/23/2008 |            | 2045 | Park Village 2545 | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 09/11/2008 | 08-09-1008 | 2128 | Cassat Hall       | Thu. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 09/11/2008 | 08-09-1011 | 2130 | Donnell Hall      | Thu. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 09/24/2008 |            | 2045 | Park Village 2525 | Wed. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |

|            |            |      |                   |      |  |   |
|------------|------------|------|-------------------|------|--|---|
| 09/25/2008 | 08-09-1068 | 2030 | Park Village 2455 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | (2) students failed to leave within two minutes |
| 09/25/2008 | 08-09-1068 | 2100 | Aitchison Hall    | Thu. | fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors   | All students evacuated within two minutes       |
| 09/25/2008 |            | 2100 | Park Village 2535 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 09/25/2008 |            | 2120 | Park Village 2545 | Thu. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 09/26/2008 | 08-09-1075 | 2055 | Park Village 2475 | Fri. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |
| 09/26/2008 | 08-09-1075 | 2120 | Park Village 2465 | Fri. | fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water) | All students evacuated within two minutes       |