

University of Dubuque 2014-2017 Fire Drill Report

2017 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
04/26/2017	17-04-0154	1720 to 1735	Aitchison Hall (701 Auburn Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (44) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.
04/26/2017	17-04-0154	1650 to 1710	Cassat Hall (2200 Bennett Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (18) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
			Chlapaty Hall (80 Dodge Street)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted. This building has (126) fire safety devices, and (59) illuminated signs.
04/26/2017	17-04-0154	1618 to 1635	Donnell Hall (2250 Bennett Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (18) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
11/15/2017	17-11-0453	1540 to 1544	Park Village 2455 (2455 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (19) evacuated within the two minutes. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
11/15/2017	17-11-0453	1531 1535	Park Village 2465 (2465 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (33) evacuated within the two minutes. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
11/15/2017	17-11-0453	1518 to 1522	Park Village 2475 (2475 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (17) evacuated within the two minutes. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.

11/15/2017	17-11-0454	1551 to 1554	Park Village 2525 (2525 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (13) evacuated within the two minutes. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
11/15/2017	17-11-0454	1556 to 1600	Park Village 2535 (2535 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (15) evacuated within the two minutes. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
11/15/2017	17-11-0454	1602 to 1605	Park Village 2545 (2545 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (6) evacuated within the two minutes. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. This building has (1) illuminated sign. One additional illuminated sign is needed.

04/17/2017	17-04-0142	1152 to 1156	Blades Hall (1171 N. Algona St.)	Mon.	fire alarm panel, smoke detector, horns, fire extinguisher	All (81) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. This building has (13) fire safety devices, and (6) illuminated signs.
04/17/2017	17-04-0142	1337 to 1341	Chlapaty Wellness Center (150 McCormick Street Extension)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (69) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (6) fire safety devices failed to function correctly.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff. This building has (8) fire safety devices, and (3) illuminated signs.
04/17/2017	17-04-0142	1140 to 1145	Dunlap Technology Building (1250 McCormick St.)	Mon.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (130) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
04/17/2017	17-04-0142	1414 to 1420	Goldthorp Science Hall (1150 N. Algona St.)	Mon.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (86) evacuated within the two minutes. All (87) fire safety devices, and (29) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices. The (1) illuminated sign worked as anticipated.
04/17/2017	17-04-0142	1429 to 1440	Heritage Center (2255 Bennett Street)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (65) evacuated within the two minutes. All (101) fire safety devices, and (49) illuminated signs performed as anticipated. (1) device failed to function correctly
04/17/2017	17-04-0142	1200 to 1204	Hub (1025 N. Algona Street)	Mon.	fire extinguishers	All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
04/17/2017	17-04-0142	1128 to 1130	McCormick/Stoltz Gym (1250 McCormick St.)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (23) evacuated within the two minutes. (35) fire safety devices, and (38) illuminated signs performed as anticipated. (6)safety devices failed to function correctly
04/17/2017	17-04-0142	1326 to 1331	Mercer/Birmingham Hall (205 McCormick Street Extension)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (40) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.

04/17/2017	17-04-0142	1220 to 1226	Myers Building MTAC (455 North Algona)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (123) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated.
04/17/2017	17-04-0142	1115 to 1121	Myers Library (2105 Grace Street)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (88) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm <u>inside their area.</u>
04/17/2017	17-04-0142	1405 to 1410	Peters Commons (1100 N. Algona St.)	Mon.	fire alarm panel, strobe lights, horns, fire extinguishers	All (31) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.
04/17/2017	17-04-0142	1210 to 1205	Severance Hall (1000 N. Algona St.)	Mon.	fire alarm panel, strobe lights, horns, fire extinguishers	All (34) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm <u>inside their area.</u>
04/17/2017	17-04-0142	1110 to 1112	Smith Hall (2205 Grace Street)	Mon.	horns, fire extinguishers	All (15) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
04/17/2017	17-04-0142	1200 to 1204	Van Vliet Hall (1025 N. Algona St.)	Mon.	Fire alarm panel, horns, fire extinguishers	All (20) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.
04/17/2017	17-04-0142	1346 to 1348	Veteran's Memorial Training Center (90 McCormick Str.) Opened (01/15/2014)	Mon.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (1) evacuated within the two minutes. All (27) fire safety devices, and (3) illuminated signs performed as anticipated.
04/17/2017	17-04-0142	1446 to 1448	Visitor's Bleachers and Concessions	Mon.	smoke detector, heat detector, strobe lights, horns, fire extinguisher	(0) empty. All (7) fire safety devices, and (2) illuminated signs performed as anticipated.

2017 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
09/14/2017	17-09-0318	1659 to 1714	Aitchison Hall (701 Auburn Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (60) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.
09/14/2017	17-09-0318	1719 to 1728	Cassat Hall (2200 Bennett Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (38) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.

09/21/2017	17-09-0325	1713 to 1722	Chlapaty Hall (80 Dodge Street)	Sun.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (51) evacuated within the two minutes. All (157) fire safety devices, and (57) illuminated signs performed as anticipated.
09/14/2017	17-09-0318	1731 to 1744	Donnell Hall (2250 Bennett Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (48) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
11/15/2017	17-11-0453	1540 to 1544	Park Village 2455 (2455 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (19) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
11/15/2017	17-11-0453	1531 to 1535	Park Village 2465 (2465 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (33) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
11/15/2017	17-11-0453	1518 to 1522	Park Village 2475 (2475 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (17) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
11/15/2017	17-11-0454	1551 to 1554	Park Village 2525 (2525 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (13) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
11/15/2017	17-11-0454	1556 to 1600	Park Village 2535 (2535 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (15) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.

11/15/2017	17-11-0454	1602 to 1605	Park Village 2545 (2545 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (6) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed.
10/05/2017	17-10-0357	1206 to 1210	Blades Hall (1171 N. Algona St.)	Thur.	fire alarm panel, smoke detector, horns, fire extinguisher	All (35) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. This building has (13) fire safety devices, and (6) illuminated signs.
10/05/2017	17-10-0357	1413 to 1420	Chlapaty Wellness Center (150 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (80) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. In the bleachers level (6) strobes failed to function and only (2) speakers sounded.

			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff. This building has (8) fire safety devices, and (3) illuminated signs.
10/05/2017	17-10-0357	1159 to 1204	Dunlap Technology Building (1250 McCormick St.)	Thur.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (57) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated. Outside bell on West side of building failed to function.
10/05/2017	17-10-0357	1344 to 1350	Goldthorp Science Hall (1150 N. Algona St.)	Thur.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (137) evacuated within the two minutes. All (87) fire safety devices, and (29) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices. The (1) illuminated sign worked as anticipated.
			Heritage Center (2255 Bennett Street)		fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	No fire drill was conducted. This building has (102) fire safety devices, and (49) illuminated signs.
10/05/2017	17-10-0357	1213 to 1215	Hub (1025 N. Algona Street)	Thur.	fire extinguishers	All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices. All (5) illuminated signs worked as anticipated.
10/05/2017	17-10-0357	1145 to 1150	McCormick/Stoltz Gym (1050 McCormick St.)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (18) evacuated within the two minutes. All (41) fire safety devices, and (38) illuminated signs performed as anticipated.
10/05/2017	17-10-0357	1235 to 1240	Mercer/Birmingham Hall (205 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (31) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
10/05/2017	17-10-0357	1250 to 1256	Myers Building MTAC (455 North Algona)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (160) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated. Exterior strobe on the East side failed to function.

10/05/2017	17-10-0357	1132 to 1138	Myers Library (2105 Grace Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (131) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.
10/05/2017	17-10-0357	1355 to 1401	Peters Commons (1100 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	All (44) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.
10/05/2017	17-10-0357	1219 to 1224	Severance Hall (1000 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	All (83) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
10/05/2017	17-10-0357	1127 to 1129	Smith Hall (2205 Grace Street)	Thur.	horns, fire extinguishers	All (17) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
10/05/2017	17-10-0357	1206 to 1210	Van Vliet Hall (1025 N. Algona St.)	Thur.	Fire alarm panel, horns, fire extinguishers	All (16) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.16
10/05/2017	17-10-0357	1424 to 1426	Veteran's Memorial Training Center Practice Field House (90 McCormick Street) Opened (01/15/2014)	Thur.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (4) evacuated within the two minutes. All (27) fire safety devices, and (3) illuminated signs performed as anticipated.
10/05/2017	17-10-0357	1410 to 1412	Visitor's Bleachers and Concessions	Thur.	smoke detector, heat detector, strobe lights, horns, fire extinguisher	Nonone was inside to evacuate. The building has (9) fire safety devices, and (2) illuminated signs. The only device that was functioning was in the North end side.

2016 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
05/02/2016	16-05-0168	1530 to 1547	Aitchison Hall (701 Auburn Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (48) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.
05/02/2016	16-05-0168	1550 to 1605	Cassat Hall (2200 Bennett Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (46) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.

05/05/2016	16-05-0173	1855 to 1912	Chlapaty Hall (80 Dodge Street)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (52) evacuated within the two minutes. All (126) fire safety devices, and (59) illuminated signs performed as anticipated.
05/02/2016	16-05-0168	1610 to 1617	Donnell Hall (2250 Bennett Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (37) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
05/02/2016	16-05-0168	1725 to 1740	Park Village 2455 (2455 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (7) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
05/02/2016	16-05-0168	1705 to 1720	Park Village 2465 (2465 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (11) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
05/02/2016	16-05-0168	1745 to 1810	Park Village 2475 (2475 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (16) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
05/05/2016	16-05-0173	1605 to 1617	Park Village 2525 (2525 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (12) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
05/05/2016	16-05-0173	1625 to 1641	Park Village 2535 (2535 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (21) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.

05/05/2016	16-05-0173	1644 to 1658	Park Village 2545 (2545 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (13) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. One additional illuminated sign is needed.
04/14/2016	16-04-0134	1138 to 1141	Blades Hall (1171 N. Algona St.)	Thur.	fire alarm panel, smoke detector, horns, fire extinguisher	All (85) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
04/14/2016	16-04-0134	1358 to 1401	Chlapaty Wellness Center (150 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (45) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (6) strobes, and (2) speakers failed to function
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff. (8) fire safety devices, and (3) illuminated signs.
04/14/2016	16-04-0134	1129 to 1133	Dunlap Technology Building (1250 McCormick St.)	Thur.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (64) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.

04/14/2016	16-04-0134	1331 to 1337	Goldthorp Science Hall (1150 N. Algona St.)	Thur.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (58) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
04/14/2016	16-04-0134	1422 to 1430	Heritage Center (2255 Bennett Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (75) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated. (1) fire safety device failed to function
04/14/2016	16-04-0134	1124 to 1126	Hub (1025 N. Algona Street)	Thur.	fire extinguishers	All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices.
04/14/2016	16-04-0134	1112 to 1117	McCormick/Stoltz Gym (1250 McCormick St.)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (35) evacuated within the two minutes. All (40) fire safety devices, and (38) illuminated signs performed as anticipated. (1) strobe failed to function.
04/14/2016	16-04-0134	1409 to 1411	Mercer/Birmingham Hall (205 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (50) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
04/14/2016	16-04-0134	1157 to 1201	Myers Building MTAC (455 North Algona)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (115) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated. (1) illuminated sign failed to work.
04/14/2016	16-04-0134	1059 to 1104	Myers Library (2105 Grace Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (176) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.
04/14/2016	16-04-0134	1343 to 1346	Peters Commons (1100 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	All (58) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.
04/14/2016	16-04-0134	1148 to 1151	Severance Hall (1000 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	All (52) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.

04/14/2016	16-04-0134	1048 to 1051	Smith Hall (2205 Grace Street)	Thur.	horns, fire extinguishers	All (12) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
04/14/2016	16-04-0134	1123 to 1125	Van Vliet Hall (1025 N. Algona St.)	Thur.	Fire alarm panel, horns, fire extinguishers	All (31) evacuated within the two minutes. All (3) fire safety devices, and (9) illuminated signs performed as anticipated.
			Veteran's Memorial Training Center (90 McCormick Str.) Opened (01/15/2014)		fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted.
			Visitor's Bleachers and Concessions		smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.

2016 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
09/22/2016	16-09-0302	1745 to 1756	Aitchison Hall (701 Auburn Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (44) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.
09/22/2016	16-09-0302	1840 to 1850	Cassat Hall (2200 Bennett Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (57) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
09/26/2016	16-10-0337	1927 to 1946	Chlapaty Hall (80 Dodge Street)	Mon.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (37) evacuated within the two minutes. All (126) fire safety devices, and (59) illuminated signs performed as anticipated.
09/22/2016	16-09-0302	1855 to 1905	Donnell Hall (2250 Bennett Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (49) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
10/05/2016	16-10-0337	2225 to 2243	Park Village 2455 (2455 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (6) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.

10/05/2016	16-10-0337	2200 to 2218	Park Village 2465 (2465 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (9) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
10/05/2016	16-10-0337	2135 to 2148	Park Village 2475 (2475 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (13) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
10/05/2016	16-10-0337	2110 to 2123	Park Village 2525 (2525 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (14) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
10/05/2016	16-10-0337	2035 to 2047	Park Village 2535 (2535 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (11) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
10/05/2016	16-10-0337	2000 to 2017	Park Village 2545 (2545 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (17) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)			No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
---------------	-------------	---------------	------------------------	-------------	-----------------------------------	---------------

			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted. (5) illuminated signs.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted. (4) illuminated signs.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted. (4) illuminated signs.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. (1) illuminated sign. One additional illuminated sign is needed.
10/18/2016	16-10-0359	1208 to 1211	Blades Hall (1171 N. Algona St.)	Tues.	fire alarm panel, smoke detector, horns, fire extinguisher	All (63) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. (13) fire safety devices, and (6) illuminated signs.
10/18/2016	16-10-0359	1310 to 1316	Chlapaty Wellness Center (150 McCormick Street Extension)	Tues.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (27) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (6) safety devices failed to function correctly.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff. (8) fire safety devices, and (3) illuminated signs.
10/18/2016	16-10-0359	1215 to 1220	Dunlap Technology Building (1250 McCormick St.)	Tues.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (79) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
10/18/2016	16-10-0359	1328 to 1335	Goldthorp Science Hall (1150 N. Algona St.)	Tues.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (168) evacuated within the two minutes. All (87) fire safety devices, and (29) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. The (1) illuminated sign.
10/18/2016	16-10-0359	1400 to 1406	Heritage Center (2255 Bennett Street)	Tues.	fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (77) evacuated within the two minutes. All (101) fire safety devices, and (49) illuminated signs performed as anticipated. (1) exterior safety device failed to function correctly
10/18/2016	16-10-0359	1136 to 1138	Hub (1025 N. Algona Street)		fire extinguishers	All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.

			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices. (5) illuminated signs.
10/18/2016	16-10-0359	1127 to 1130	McCormick/Stoltz Gym (1050 McCormick St.)	Tues.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (42) evacuated within the two minutes. All (40) fire safety devices, and (38) illuminated signs performed as anticipated. (1) exterior strobe failed to function correctly.
10/18/2016	16-10-0359	1300 to 1305	Mercer/Birmingham Hall (205 McCormick Street Extension)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (65) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
10/18/2016	16-10-0359	1152 to 1158	Myers Building MTAC (455 North Algona)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (162) evacuated within the two minutes. All (42) fire safety devices, and (23) illuminated signs performed as anticipated. (1) exterior sounder fail to function correctly.
10/18/2016	16-10-0359	1116 to 1121	Myers Library (2105 Grace Street)	Tues.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (131) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.
10/18/2016	16-10-0359	1345 to 1350	Peters Commons (1100 N. Algona St.)	Tues.	fire alarm panel, strobe lights, horns, fire extinguishers	All (37) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.
10/18/2016	16-10-0359	1142 to 1147	Severance Hall (1000 N. Algona St.)	Tues.	fire alarm panel, strobe lights, horns, fire extinguishers	All (48) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
10/18/2016	16-10-0359	1109 to 1112	Smith Hall (2205 Grace Street)	Tues.	horns, fire extinguishers	All (15) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
10/18/2016	16-10-0359	1135 to 1138	Van Vliet Hall (1025 N. Algona St.)	Tues.	Fire alarm panel, horns, fire extinguishers	All (13) evacuated within the two minutes. All (3) fire safety devices, and (9) illuminated signs performed as anticipated.
			Veteran's Memorial Training Center Practice Field House (90 McCormick Street) Opened (01/15/2014)		fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted. (26) fire safety devices, and (3) illuminated signs.
			Visitor's Bleachers and Concessions		smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. (9) fire safety devices, and (3) illuminated signs.

2015 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
04/07/2015	15-04-0124	1917 to 1944	Aitchison Hall (701 Auburn Street)	Tues.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (39) evacuated within the two minutes. All (129) fire safety devices, and (12) illuminated signs performed as anticipated. (1) fire safety devices (interior sounders) failed to function correctly.
04/27/2015	15-04-0161	2045 to 2120	Cassat Hall (2200 Bennett Street)	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (56) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
05/04/2015	15-05-0172	1859 to 1912	Chlapaty Hall (80 Dodge Street)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (42) evacuated within the two minutes. All (175) fire safety devices, and (57) illuminated signs performed as anticipated.
04/27/2015	15-04-0161	2137 to 2145	Donnell Hall (2250 Bennett Street)	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (45) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
05/05/2015	15-05-0175	1850 to 1902	Park Village 2455 (2455 Dodge Street)	Tues.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (7) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
05/05/2015	15-05-0175	1850 to 1900	Park Village 2465 (2465 Dodge Street)	Tues.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (18) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
05/05/2015	15-05-0172	1935 to 1947	Park Village 2475 (2475 Dodge Street)	Mon.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (32) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.

05/05/2015	15-05-0175	1909 to 1913	Park Village 2525 (2525 Dodge Street)	Tues.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (7) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
05/05/2015	15-05-0175	1914 to 1920	Park Village 2535 (2535 Dodge Street)	Tues.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (10) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
05/05/2015	15-05-0175	1921 to 1928	Park Village 2545 (2545 Dodge Street)	Tues.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (5) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C ()		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service.
03/20/2015	15-03-0103	1325 to 1330	Blades Hall (1171 N. Algona St.)	Fri.	fire alarm panel, smoke detector, horns, fire extinguisher	All (4) evacuated within the two minutes. All (8) fire safety devices, and (8) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. Building has (13) fire safety devices, and (6) illuminated signs.

05/04/2015	15-05-0173	1423 to 1429	Chlapaty Wellness Center (150 McCormick Street Extension)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (67) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs performed as anticipated. (7) strobes failed to perform as required.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff.
05/06/2015	15-05-0179	1315 to 1319	Dunlap Technology Building (1250 McCormick St.)	Tue.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (51) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
05/06/2015	15-05-0179	1303 to 1307	Goldthorp Science Hall (1150 N. Algona St.)	Tue.	fire alarm panel,battery back-up,smoke detector,heat detector,strobe lights,horns,fire extinguisher,fire door,sprinkler system-water	All (146) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
03/20/2015	15-03-0103	1354 to 1359	Heritage Center (2255 Bennett Street)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (29) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated.
			Hub (1025 N. Algona Street)		fire extinguishers	No fire drill was conducted. Staff can not hear the alarm inside their area.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
03/20/2015	15-03-0103	1310 to 1320	McCormick/Stoltz Gym (1250 McCormick St.)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (5) evacuated within the two minutes. All (33) fire safety devices, and (36) illuminated signs performed as anticipated. (1) fire safety devices (exterior horn/strobe) failed to function correctly.
05/04/2015	15-05-0173	1417 to 1419	Mercer/Birmingham Hall (205 McCormick Street Extension)	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (17) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
03/20/2015	15-03-0103	1412 to 1420	Myers Building MTAC (455 North Algona)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (23) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated. (1) fire safety device (exterior horn/strobe) failed to function correctly.

05/06/2015	15-05-0179	1325 to 1337	Myers Library (2105 Grace Street)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (137) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.
03/20/2015	15-03-0103	1340 to 1347	Peters Commons (1100 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (8) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the Snack Bar area.
03/20/2015	15-03-0103	1300 to 1305	Severance Hall (1000 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (15) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
03/20/2015	15-03-0103	1246 to 1249	Smith Hall (2205 Grace Street)	Fri.	horns, fire extinguishers	All (3) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
03/20/2015	15-03-0103	1253 to 1257	Van Vliet Hall (1025 N. Algona St.)	Fri.	Fire alarm panel, horns, fire extinguishers	All (4) evacuated within the two minutes. All (3) fire safety devices, and (8) illuminated signs performed as anticipated.
03/20/2015	15-03-0103	1105 to 1115	Veteran's Memorial Training Center (90 McCormick Str.) Opened (01/15/2014)	Fri.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No one was inside the building. All (26) fire safety devices, and (3) illuminated signs performed as anticipated. (1) fire safety device (exterior horn/strobe) failed to function correctly.

2015 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
10/05/2015	15-10-0307	1935 to 1943	Aitchison Hall (701 Auburn Street)	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (60) evacuated within the two minutes. All (136) fire safety devices, and (12) illuminated signs performed as anticipated.
10/05/2015	15-10-0307	2009 to 2016	Cassat Hall (2200 Bennett Street)	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (47) evacuated within 3.5 minutes(not an acceptable time of two minutes), one student refused to leave. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.

10/20/2015	15-10-0339	1859 to 1912	Chlapaty Hall (80 Dodge Street)	Tue.	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (74) evacuated within 3.5 minutes(not an acceptable time of two minutes). All (126) fire safety devices, and (59) illuminated signs performed as anticipated.
10/05/2015	15-10-0307	1955 to 2003	Donnell Hall (2250 Bennett Street)	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (68) evacuated within three minutes(not an acceptable time of two minutes). All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
10/20/2015	15-10-0339	1925 to 1936	Park Village 2455 (2455 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (11) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
10/20/2015	15-10-0339	1937 to 1943	Park Village 2465 (2465 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (13) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
10/20/2015	15-10-0339	1937 to 1943	Park Village 2475 (2475 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (16) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
10/20/2015	15-10-0339	1608 to 1617	Park Village 2525 (2525 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (8) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
10/20/2015	15-10-0339	1625 to 1632	Park Village 2535 (2535 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (14) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.

10/20/2015	15-10-0339	1634 to 1638	Park Village 2545 (2545 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (3) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C ()		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted. (5) illuminated signs.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted. (4) illuminated signs.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted. (4) illuminated signs.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. (1) illuminated sign. One additional illuminated sign is needed.
10/06/2015	15-10-0315	1418 to 1420	Blades Hall (1171 N. Algona St.)		fire alarm panel, smoke detector, horns, fire extinguisher	All (45) evacuated within the two minutes. All (25) fire safety devices, and (9) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Rd NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted. Building has (13) fire safety devices, and (6) illuminated signs.
10/07/2015	15-10-0315	1418 to 1430	Chlapaty Wellness Center (150 McCormick Street Extension)	Wed	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (95) evacuated within the two minutes. All (73) fire safety devices, and (17) illuminated signs performed as anticipated. (8) strobe lights failed to function correctly.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff. (8) fire safety devices, and (3) illuminated signs.
10/06/2015	15-10-0315	1426 to 1431	Dunlap Technology Building (1250 McCormick St.)		fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (55) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.

10/06/2015	15-10-0315	1334 to 1339	Goldthorp Science Hall (1150 N. Algona St.)	Tue.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (107) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
10/08/2015	15-10-0315	1425 to 1431	Heritage Center (2255 Bennett Street)	Thur.	fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (84) evacuated within the two minutes. All (101) fire safety devices, and (49) illuminated signs performed as anticipated. (1) safety device failed to function correctly.
10/06/2015	15-10-0315	1409 1413	Hub (1025 N. Algona Street)	Tue.	fire extinguishers	Staff can not hear the alarm inside their area. All (2) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices. Building has (5) illuminated signs.
10/06/2015	15-10-0315	1323 to 1326	McCormick/Stoltz Gym (1050 McCormick St.)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (31) evacuated within the two minutes. All (33) fire safety devices, and (37) illuminated signs performed as anticipated.
10/07/2015	15-10-0315	1406 to 1408	Mercer/Birmingham Hall (205 McCormick Street Extension)	Wed	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (88) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
10/06/2015	15-10-0315	1439 to 1445	Myers Building MTAC (455 North Algona)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (97) evacuated within the two minutes. All (43) fire safety devices, and (22) illuminated signs performed as anticipated. (1) illuminated sign failed to function correctly.
10/06/2015	15-10-0315	1302 to 1308	Myers Library (2105 Grace Street)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (140) evacuated within the two minutes. (33) fire safety devices, and (35) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area. (2) illuminated signs failed to function correctly.
10/06/2015	15-10-0315	1350 to 1352	Peters Commons (1100 N. Algona St.)	Tue.	fire alarm panel, strobe lights, horns, fire extinguishers	All (28) evacuated within the two minutes. All (45) fire safety devices, and (15) illuminated signs performed as anticipated.

10/06/2015	15-10-0315	1400-1404	Severance Hall (1000 N. Algona St.)	Tue.	fire alarm panel, strobe lights, horns, fire extinguishers	All (40) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
10/06/2015	15-10-0315	1255 to 1259	Smith Hall (2205 Grace Street)	Tue.	horns, fire extinguishers	All (14) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
10/06/2015	15-10-0315	1409 to 1413	Van Vliet Hall (1025 N. Algona St.)	Tue.	Fire alarm panel, horns, fire extinguishers	All (20) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.
10/07/2015	15-10-0315	1434 to 1436	Veteran's Memorial Training Center Practice Field House (90 McCormick Street) Opened (01/15/2014)	Wed	fire alarm panel, battery back-up, monitor (external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (2) evacuated within the two minutes. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.

2014 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
04/25/2014	14-04-0138	2002 to 2044	Aitchison Hall (701 Auburn Street)	Fri.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (58) evacuated within the two minutes. All (135) fire safety devices, and (12) illuminated signs performed as anticipated. (1) sounder failed to function correctly.
04/25/2014	14-04-0138	2045 to 2120	Cassat Hall (2200 Bennett Street)	Fri.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (71) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
04/25/2014	14-04-0138	2137 to 2145	Donnell Hall (2250 Bennett Street)	Fri.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (58) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
04/30/2014	14-04-0141	2100 to	Park Village 2455	Wed.	fire panel, battery back-up, monitor(external	All (12) evacuated within the two minutes. All
04/30/2014	14-04-0141	2045 to 2052	Park Village 2465 (2465 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (12) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.

04/30/2014	14-04-0141	2030 to 2043	Park Village 2475 (2475 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (25) evacuated within the two minutes. All (14) fire safety devices, and (9) illuminated signs performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
04/30/2014	14-04-0141	1955 to 2008	Park Village 2525 (2525 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (16) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
04/30/2014	14-04-0141	2012 to 2023	Park Village 2535 (2535 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (9) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
04/30/2014	14-04-0141	1900 to 1920	Park Village 2545 (2545 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (9) evacuated within the two minutes. All (2) fire safety devices, and (5) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.

			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. One additional illuminated sign is needed.
04/09/2014	14-04-0107	1342 to 1346	Blades Hall (1171 N. Algona St.)	Wed.	fire alarm panel, smoke detector, horns, fire extinguisher	All (53) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Road NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
04/25/2014	14-04-0129	1148 to 1155	Chlapaty Wellness Center (150 McCormick Street Extension)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (23) evacuated within the two minutes. All (76) fire safety devices, and (16) illuminated signs performed as anticipated, (6) fire safety devices failed to function correctly.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff.
04/09/2014	14-04-0107	1333 to 1335	Dunlap Technology Building (1250 McCormick St.)	Wed.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (49) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
04/25/2014	14-04-0129	1328 to 1332	Goldthorp Science Hall (1150 N. Algona St.)	Fri.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (41) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.
			Heritage Center (2255 Bennett Street)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted. This building has (102) fire safety devices, and (49) illuminated signs.
04/09/2014	14-04-0107	1414 to 1419	Hub (1025 N. Algona Street)	Wed.	fire extinguishers	Staff can not hear the alarm inside their area. All (3) evacuated within the two minutes. All (3) fire safety devices, and (2) illuminated signs performed as anticipated.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices.
04/09/2014	14-04-0107	1322 to 1327	McCormick/Stoltz Gym (1250 McCormick St.)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (18) evacuated within the two minutes. All (33) fire safety devices, and (37) illuminated signs performed as anticipated.

04/25/2014	14-04-0129	1140 to 1142	Mercer/Birmingham Hall (205 McCormick Street Extension)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (45) evacuated within the two minutes. All (24) fire safety devices, and (7) illuminated signs performed as anticipated.
			Myers Building MTAC (455 North Algona)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	No fire drill was conducted. This building has (43) fire safety devices, and (30) illuminated signs.
04/25/2014	14-04-0129	1110 to 1118	Myers Library (2105 Grace Street)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (69) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm <u>inside their area.</u>
04/09/2014	14-04-0107	1357 to 1400	Peters Commons (1100 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	All (21) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the <u>Snack Bar area.</u>
04/09/2014	14-04-0107	1405 to 1407	Severance Hall (1000 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	All (34) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm <u>inside their area.</u>
04/09/2014	14-04-0107	1315 to 1318	Smith Hall (2205 Grace Street)	Wed.	horns, fire extinguishers	All (10) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
04/09/2014	14-04-0107	1414 to 1419	Van Vliet Hall (1025 N. Algona St.)	Wed.	Fire alarm panel, horns, fire extinguishers	All (25) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.
04/25/2014	14-04-0129	1204 to 1210	Veteran's Memorial Training Center (90 McCormick Street) Opened (01/15/2014)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	Building was empty. All (26) fire safety devices, and (3) illuminated signs performed as anticipated.

2014 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
12/11/2014	14-12-0360	2002 to 2020	Aitchison Hall (701 Auburn Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (69) evacuated within the two minutes. Only (133) fire safety devices, and (12) illuminated signs performed as anticipated. Three sounders failed to work correctly

12/11/2014	14-12-0362	1940 to 1954	Cassat Hall (2200 Bennett Street)	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (83) evacuated within the two minutes. All (25) fire safety devices, and (10) illuminated signs performed as anticipated.
			Donnell Hall (2250 Bennett Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	No fire drill was conducted. This building has (25) fire safety devices, and (10) illuminated signs.
			Chlapaty Hall (80 Dodge Street) Opened (08/15/14)		fire panel, battery back-up, monitor(external vendor), monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted.
			Park Village 2455 (2455 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard.</u>
			Park Village 2465 (2465 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard.</u>
			Park Village 2475 (2475 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (14) fire safety devices, and (9) illuminated signs. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard.</u>
			Park Village 2525 (2525 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>
			Park Village 2535 (2535 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>
			Park Village 2545 (2545 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. This building has (2) fire safety devices, and (5) illuminated signs. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common <u>area inside the suites.</u>

			Potterveld A () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld B () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.
			Potterveld C () (Demolished 06/06/13)		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building was demolished 06/06/13.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices. The (1) illuminated sign worked as anticipated. One additional illuminated sign is needed.
10/24/2014	14-10-0296	1401 to 1405	Blades Hall (1171 N. Algona St.)		fire alarm panel, smoke detector, horns, fire extinguisher	All (28) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.
			Cedar Rapids Campus (294 Blairs Ferry Road NE)		fire alarm panel, battery back-up, monitor (external vendor), smoke detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
10/30/2014	14-10-0309	1433 to 1438	Chlapaty Wellness Center (150 McCormick Street Extension)	Thu.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (70) evacuated within the two minutes. All (81) fire safety devices, and (17) illuminated signs, 6 strobes malfunctioned.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only done by Daycare staff.
10/24/2014	14-10-0296	1411 to 1415	Dunlap Technology Building (1250 McCormick St.)	Fri.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (72) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
10/24/2014	14-10-0296	1442 to 1450	Goldthorp Science Hall (1150 N. Algona St.)	Fri.	fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system-water	All (153) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.

			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.
			Heritage Center (2255 Bennett Street)		fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system (water)	No fire drill was conducted. This building has (102) fire safety devices, and (49) illuminated signs.
			Hub (1025 N. Algona Street)		fire extinguishers	No fire drill was conducted. Staff can not hear the alarm inside their area. This building has no fire safety devices. This building has (2) illuminated signs. One additional illuminated sign is needed.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices. Building has (5) illuminated signs.
10/30/2014	14-10-0309	1352 to 1357	McCormick/Stoltz Gym (1050 McCormick St.)	Thu.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (18) evacuated within the two minutes. All (33) fire safety devices, and (36) illuminated signs performed as anticipated.
10/30/2014	14-10-0309	1443 to 1445	Mercer/Birmingham Hall (205 McCormick Street Extension)	Thu.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (29) evacuated within the two minutes. All (24) fire safety devices, and (8) illuminated signs performed as anticipated.
10/30/2014	14-10-0309	1418 to 1423	Myers Building MTAC (455 North Algona)	Thu.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (186) evacuated within the two minutes. All (43) fire safety devices, and (23) illuminated signs performed as anticipated.
10/30/2014	14-10-0309	1402-1407	Myers Library (2105 Grace Street)	Thu.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (137) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center (ASC) can not hear the alarm inside their area.
10/24/2014	14-10-0296	1356 to 1359	Peters Commons (1100 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (38) evacuated within the two minutes. All (6) fire safety devices, and (13) illuminated signs performed as anticipated. No horns inside the Snack Bar area.
10/24/2014	14-10-0296	1427 to 1432	Severance Hall (1000 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (54) evacuated within the two minutes. All (10) fire safety devices, and (17) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.

10/30/2014	14-10-0309	1345 to 1348	Smith Hall (2205 Grace Street)	Thu.	horns, fire extinguishers	All (23) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
10/24/2014	14-10-0296	1419 to 1422	Van Vliet Hall (1025 N. Algona St.)	Fri.	Fire alarm panel, horns, fire extinguishers	All (32) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.
			Veteran's Memorial Training Center (90 McCormick Street) Opened (01/15/2014)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	No fire drill was conducted. This building has (26) fire safety devices, and (3) illuminated signs.

2013 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
05/01/2013	13-05-0185	1706	Aitchison Hall (701 Auburn Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (54) evacuated within the two minutes. All (136) fire safety devices performed as anticipated.
05/01/2013	13-05-0185	1729	Cassat Hall (2200 Bennett Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (28) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.
05/01/2013	13-05-0185	1740	Donnell Hall (2250 Bennett Street)	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (36) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.
05/01/2013	13-05-0185	1808	Park Village 2455 (2455 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (14) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard</u>
05/01/2013	13-05-0185	1817	Park Village 2465 (2465 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (17) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway <u>audible could barely be heard</u> .

05/01/2013	13-05-0185	1834	Park Village 2475 (2475 Dodge Street)	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (20) evacuated within the two minutes. All (14) fire safety devices performed as anticipated. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
			Park Village 2525 (2525 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2535 (2535 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2545 (2545 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- Americas Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service.
04/29/2013	13-05-0185	1329	Blades Hall (1171 N. Algona St.)	Tue.	fire alarm panel, smoke detector, horns, fire extinguisher	All (28) evacuated within the two minutes. All (8) fire safety devices performed as anticipated.
04/26/2013	13-04-0179	1305	Chlapaty Wellness Center (150 McCormick Street Extension)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (26) evacuated within the two minutes. All (77 out of 81) fire safety devices performed as anticipated. (4) strobes failed to function as anticipated.

			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
04/26/2013	13-04-0179	1356	Dunlap Technology Building (1250 McCormick St.)	Fri.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (42) evacuated within the two minutes. All (9) fire safety devices performed as anticipated.
04/29/2013	13-05-0185	1340	Goldthorp Science Hall (1150 N. Algona St.)	Tue.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All (111) evacuated within the two minutes. All (60) fire safety devices performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
			Heritage Center (2255 Bennett Street) (Open 04/10/2013)		fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	No fire drill was conducted
04/26/2013	13-04-0179	1350	Hub	Fri.	fire extinguishers	Staff can not hear the alarm inside their area. All evacuated within the two minutes.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
04/26/2013	13-04-0179	1328	McCormick/Stoltz Gym (1050 McCormick St.)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (17) evacuated within the two minutes. All (27) fire safety devices performed as anticipated.
04/26/2013	13-04-0179	1318	Mercer/Birmingham Hall (205 McCormick Street Extension)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	All (15) evacuated within the two minutes. All (24) fire safety devices performed as anticipated.
04/26/2013	13-04-0179	1425	Myers Building MTAC (455 North Algona)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (52) evacuated within the two minutes. All (43) fire safety devices performed as anticipated.
04/26/2013	13-04-0179	1339	Myers Library (2105 Grace Street)	Fri.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (92) evacuated within the two minutes. All (44) fire safety devices performed as anticipated. Staff of the Academic Success Center can not hear the alarm inside their area. Emergency exit door malfunctioned.
04/26/2013	13-04-0179	1415	Peters Commons (1100 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (25) evacuated within the two minutes. All (6) fire safety devices performed as anticipated. No horns inside the Snack Bar area.

04/26/2013	13-04-0179	1405	Severance Hall (1000 N. Algona St.)	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All (18) evacuated within the two minutes. All (10) fire safety devices performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
04/26/2013	13-04-0179	1255	Smith Hall	Fri.	horns, fire extinguishers	All (13) evacuated within the two minutes. All (3)
04/26/2013	13-04-0179	1350	Van Vliet Hall (1025 N. Algona St.)	Fri.	Fire alarm panel, horns, fire extinguishers	All (9) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.

2013 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
			Aitchison Hall (701 Auburn Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	No fire drill was conducted.
			Cassat Hall (2200 Bennett Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	No fire drill was conducted.
			Donnell Hall (2250 Bennett Street)		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	No fire drill was conducted.
			Park Village 2455 (2455 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
			Park Village 2465 (2465 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.
			Park Village 2475 (2475 Dodge Street)		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted. When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard.

11/19/2013	13-11-0403	1730	Park Village 2525 (2525 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (25) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
11/19/2013	13-11-0403	1755	Park Village 2535 (2535 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (28) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
11/19/2013	13-11-0403	1840	Park Village 2545 (2545 Dodge Street)	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (8) evacuated within the two minutes. All (2) fire safety devices, and (4) illuminated signs performed as anticipated. The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building demolished 05/15/2013
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted. Building demolished 05/15/2013

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- America Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service. This building has no fire safety devices.
10/03/2013	13-10-0323	1427-1431	Blades Hall (1171 N. Algona St.)	Thur.	fire alarm panel, smoke detector, horns, fire extinguisher	All (45) evacuated within the two minutes. All (8) fire safety devices, and (10) illuminated signs performed as anticipated.

10/09/2013	13-10-0347	1419-1424	Chlapaty Wellness Center (150 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (23) evacuated within the two minutes. All (76 out of 81) fire safety devices, and (16) illuminated signs performed as anticipated. (5) Fire safety devices failed to function as anticipated.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
10/03/2013	13-10-0323	1435-1439	Dunlap Technology Building (1250 McCormick St.)	Thur.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (16) evacuated within the two minutes. All (9) fire safety devices, and (14) illuminated signs performed as anticipated.
10/14/2013	13-10-0347	1329-1335	Goldthorp Science Hall (1150 N. Algona St.)	Mon.	fire alarm panel,battery back-up,smoke detector,heat detector,strobe lights,horns,fire extinguisher,fire door,sprinkler system-water	All (200) evacuated within the two minutes. All (60) fire safety devices, and (20) illuminated signs performed as anticipated.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems. This building has no fire safety devices.
10/14/2013	13-10-0347	1415-1423	Heritage Center (2255 Bennett Street) (Open 04/10/2013)	Mon.	fire alarm panel, battery back-up, Monitor external vendor, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (68) evacuated within the two minutes. All (102) fire safety devices, and (49) illuminated signs performed as anticipated.
			Hub		fire extinguishers	No fire drill was conducted. Staff can not hear the alarm inside their area. This building has no fire safety devices.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted. This building has no fire safety devices.
10/03/2013	13-10-0323	1407-1413	McCormick/Stoltz Gym (1050 McCormick St.)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (14) evacuated within the two minutes. All (27) fire safety devices, and (16) illuminated signs performed as anticipated (2) signs malfunctioned.
10/09/2013	13-10-0347	1432-1437	Mercer/Birmingham Hall (205 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	All (49) evacuated within the two minutes. All (24) fire safety devices, and (7) illuminated signs performed as anticipated.
10/09/2013	13-10-0347	1351-1357	Myers Building MTAC (455 North Algona)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (180) evacuated within the two minutes. All (43) fire safety devices, and (30) illuminated signs performed as anticipated.

10/03/2013	13-10-0323	1350-1358	Myers Library (2105 Grace Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (126) evacuated within the two minutes. All (44) fire safety devices, and (27) illuminated signs performed as anticipated. Staff of the Academic Success Center can not hear the alarm inside their area.
10/14/2013	13-10-0347	1345-1400	Peters Commons (1100 N. Algona St.)	Mon.	fire alarm panel, strobe lights, horns, fire extinguishers	All (25) evacuated within the two minutes. All (6) fire safety devices, and (10 out of 12) illuminated signs performed as anticipated. (2) illuminated signs failed to function as anticipated. No horns inside the Snack Bar area.
10/09/2013	13-10-0347	1405-1409	Severance Hall (1000 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	All (40) evacuated within the two minutes. All (10) fire safety devices, and (18) illuminated signs performed as anticipated. The students in the back classrooms and lounge can not hear the alarm inside their area.
10/03/2013	13-10-0323	1340-1343	Smith Hall (2205 Grace Street)	Thur.	horns, fire extinguishers	All (20) evacuated within the two minutes. All (3) fire safety devices, and (6) illuminated signs performed as anticipated. Room 200 could not clearly hear the alarm.
10/03/2013	13-10-0323	1419-1424	Van Vliet Hall (1025 N. Algona St.)	Thur.	Fire alarm panel, horns, fire extinguishers	All (18) evacuated within the two minutes. All (3) fire safety devices, and (18) illuminated signs performed as anticipated.

2012 Fire Drills Spring Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
04/25/2012	12-04-0163	1850	Aitchison Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
04/25/2012	12-04-0163	1825	Cassat Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
04/18/2012	12-04-0148	1846	Donnell Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.

04/11/2012	12-04-0135	1830	Park Village 2455	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated within the two minutes.
04/11/2012	12-04-0135	1815	Park Village 2465	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated within the two minutes.
04/11/2012	12-04-0135	1800	Park Village 2475	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated within the two minutes.
04/09/2012	12-04-0132	1800	Park Village 2525	Mon.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. All evacuated within the two minutes.
04/09/2012	12-04-0132	1815	Park Village 2535	Mon.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. All evacuated within the two minutes.
04/09/2012	12-04-0132	1830	Park Village 2545	Mon.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the individual bedrooms, or in the common area inside the suites. All evacuated within the two minutes.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- America Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.

			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service.
04/11/2012	12-04-0134	1416	Blades Hall (1171 N. Algona St.)	Wed.	fire alarm panel, smoke detector, horns, fire extinguisher	All evacuated within the two minutes.
04/12/2012	12-04-0136	1131	Chlapaty Wellness Center (150 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	The strobes did not activate outside the wall behind the bleachers. All evacuated within the two minutes.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
04/11/2012	12-04-0134	1354	Dunlap Technology Building (1250 McCormick St.)	Wed.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All evacuated within the two minutes.
04/12/2012	12-04-0136	1051	Goldthorp Science Hall (1150 N. Algona St.)	Thur.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All evacuated within the two minutes.
			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
04/12/2012	12-04-0136	1035	Hub	Thur.	fire extinguishers	Staff can not hear the alarm inside their area. All evacuated within the two minutes.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
04/11/2012	12-04-0134	1404	McCormick/Stoltz Gym (1050 McCormick St.)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All evacuated within the two minutes.
04/12/2012	12-04-0136	1140	Mercer/Birmingham Hall (205 McCormick Street Extension)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	All evacuated within the two minutes.
04/12/2012	12-04-0136	1118	Myers Building MTAC (455 North Algona)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.
04/12/2012	12-04-0136	1035	Myers Library (2105 Grace Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	Staff of the ASC complained that they could not hear the alarm inside their area. All evacuated within the two minutes.
04/12/2012	12-04-0136	1404	Peters Commons (1100 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	No horns inside the Snack Bar area. All evacuated within the two minutes.

04/12/2012	12-04-0136	1105	Severance Hall (1000 N. Algona St.)	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	The students in the back classrooms (101-102) and lounge can not hear the alarm inside their area. All evacuated within the two minutes.
04/11/2012	12-04-0134	1335	Smith Hall (2205 Grace Street)	Wed.	horns, fire extinguishers	Room 200 could not clearly hear the alarm. All evacuated within the two minutes.
04/11/2012	12-04-0134	1347	Van Vliet Hall (1025 N. Algona St.)	Wed.	Fire alarm panel, horns, fire extinguishers	All evacuated within the two minutes.

2012 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
10/24/2012	12-10-0410	1519 to 1527	Aitchison Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (95) evacuated within the two minutes. All (136) fire safety devices performed as anticipated.
10/24/2012	12-10-0410	1519 to 1527	Cassat Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (56) evacuated within the two minutes. All (25) fire safety devices performed as anticipated.
10/24/2012	12-10-0410	1552 to 1600	Donnell Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All (73) evacuated within the two minutes, (2) students failed to evacuate within the appropriate time. All (25) fire safety devices performed as anticipated.
10/24/2012	12-10-0410	1635 to 1640	Park Village 2455	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (17) evacuated within the two minutes. All (14) fire safety devices performed as anticipated.
10/24/2012	12-10-0410	1624 to 1629	Park Village 2465	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (22) evacuated within the two minutes. All (14) fire safety devices performed as anticipated.
10/24/2012	12-10-0410	1642 to 1648	Park Village 2475	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All (12) evacuated within the two minutes. All (14) fire safety devices performed as anticipated.
			Park Village 2525		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.

			Park Village 2535		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2545		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- America Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)		fire extinguishers	No fire drill was conducted. Building is only open when having service.
10/04/2012	12-10-0369	1422 to 1425	Blades Hall (1171 N. Algona St.)	Wed.	fire alarm panel, smoke detector, horns, fire extinguisher	All (18) evacuated within the two minutes. All (8) fire safety devices performed as anticipated.
10/04/2012	12-10-0369	1334 to 1342	Chlapaty Wellness Center (150 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (33) evacuated within the two minutes. Strobes (9) failed to work. All (71) other fire safety devices performed as anticipated.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted.
10/04/2012	12-10-0369	1429 to 1432	Dunlap Technology Building (1250 McCormick St.)	Wed.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All (54) evacuated within the two minutes. All (9) fire safety devices performed as anticipated.
10/16/2012	12-10-0396	1428 to 1435	Goldthorp Science Hall (1150 N. Algona St.)	Tue.	fire alarm panel,battery back-up,smoke detector,heat detector,strobe lights,horns,fire extinguisher,fire door,sprinkler system-water	All (154) evacuated within the two minutes. All (60) fire safety devices performed as anticipated.

			Heating Plant (755 Auburn Street)		fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
			Hub		fire extinguishers	Staff can not hear the alarm inside their area. No fire drill was conducted.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
10/16/2012	12-10-0396	1440 to 1447	McCormick/Stoltz Gym (1050 McCormick St.)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All (19) evacuated within the two minutes, (1) person failed to evacuate within the appropriate time. All (27) fire safety devices performed as anticipated.
10/16/2012	12-10-0396	1415 to 1419	Mercer/Birmingham Hall (205 McCormick Street Extension)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	All (57) evacuated within the two minutes. All (24) fire safety devices performed as anticipated.
10/16/2012	12-10-0396	1340 to 1351	Myers Building MTAC (455 North Algona)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All (96) evacuated within the two minutes. All (43) fire safety devices performed as anticipated.
10/16/2012	12-10-0396	1355 to 1401	Myers Library (2105 Grace Street)	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	Staff of the ASC could not hear the alarm inside their area. All (100) evacuated within the two minutes. All (44) fire safety devices performed as anticipated.
			Peters Commons (1100 N. Algona St.)		fire alarm panel, strobe lights, horns, fire extinguishers	No horns inside the Snack Bar area. All () evacuated within the two minutes. All () fire safety devices performed as anticipated.
10/04/2012	12-10-0369	1440 to 1445	Severance Hall (1000 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	The students in the back classrooms (101-102) and lounge can not hear the alarm inside their area. All (32) evacuated within the two minutes. All (10) fire safety devices performed as anticipated.
10/04/2012	12-10-0369	1401 to 1404	Smith Hall (2205 Grace Street)	Wed.	horns, fire extinguishers	Room 200 could not clearly hear the alarm. All (15) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.
10/04/2012	12-10-0369	1408 to 1412	Van Vliet Hall (1025 N. Algona St.)	Wed.	Fire alarm panel, horns, fire extinguishers	All (32) evacuated within the two minutes. All (3) fire safety devices performed as anticipated.

2011 Fire Drills Spring Term

Date of	Case	Time of	Hall Name	Day of	Description of Fire Safety System	Brief Summary
---------	------	---------	-----------	--------	-----------------------------------	---------------

Drill	Number	Drill	Week			
02/28/2011	11-02-0260	1822	Aitchison Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	The following sounders malfunction (Rm. 213, 215). All evacuated within the two minutes.
			Cassat Hall		fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	No fire drill was conducted.
02/17/2011	11-02-0185	1829	Donnell Hall	Tue.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
			Park Village 2455		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2465		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
03/01/2011	11-03-0262	1839	Park Village 2475	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
			Park Village 2525		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2535		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2545		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
---------------	-------------	---------------	------------------------	-------------	-----------------------------------	---------------

			Airport- America Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Alumni Hall (1131 N. Algona St.)	N/A	fire extinguishers	No fire drill was conducted. Building is only open when having service.
02/17/2011	11-02-0184	1123	Blades Hall (1171 N. Algona St.)	Thur.	fire alarm panel, smoke detector, horns, fire extinguisher	All evacuated within the two minutes.
02/23/2011	11-02-0220	1027	Chlapaty Wellness Center (150 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.
02/23/2011	11-02-0220	1100	Daycare Center (1001 McCormick St.)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	All evacuated within the two minutes.
02/17/2011	11-02-0184	1115	Dunlap Technology Building (1250 McCormick St.)	Thur.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All evacuated within the two minutes.
02/23/2011	11-02-0220	1414	Goldthorp Science Hall (1150 N. Algona St.)	Wed.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All evacuated within the two minutes.
			Heating Plant (755 Auburn Street)	N/A	fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
			Hub		fire extinguishers	No fire drill was conducted.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
02/17/2011	11-02-0184	1106	McCormick/Stoltz Gym (1050 McCormick St.)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All evacuated within the two minutes.
			Mercer/Birmingham Hall (205 McCormick Street Extension)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	No fire drill was conducted. Building is currently under construction.

			Myers Building MTAC (455 North Algona)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	No fire drill was conducted.
02/17/2011	11-02-0184	1342	Myers Library (2105 Grace Street)	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.
			Peters Commons			No fire drill was conducted.
02/23/2011	11-02-0220	1012	Severance Hall (1000 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	All evacuated within the two minutes.
02/17/2011	11-02-0184	1054	Smith Hall (2205 Grace Street)	Thur.	horns, fire extinguishers	All evacuated within the two minutes.
02/17/2011	11-02-0184	1134	Van Vliet Hall (1025 N. Algona St.)	Thur.	Fire alarm panel, horns, fire extinguishers	All evacuated within the two minutes.

2011 Fire Drills Fall Term

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
09/28/2011	11-09-0783	1830	Aitchison Hall	Wed.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	Two pull station covers, and two sounders failed to function. All evacuated within the two minutes.
09/29/2011	11-09-0785	1831	Cassat Hall	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	Pull station cover (2nd floor east side) did not function. All evacuated within the two minutes.
09/29/2011	11-09-0785	1842	Donnell Hall	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
			Park Village 2455		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2465		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2475		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.

			Park Village 2525		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2535		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Park Village 2545		fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	No fire drill was conducted.
			Potterveld A		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld B		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.
			Potterveld C		smoke detector, fire extinguisher, fire doors	No fire drill was conducted.

Date of Drill	Case Number	Time of Drill	Academic Building Name	Day of Week	Description of Fire Safety System	Brief Summary
			Airport- America Hanger (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
			Airport- Iowa Hanger (Dubuque Regional Airport)		fire extinguisher	No fire drill was conducted.
			Airport- Operations Bldg. (Dubuque Regional Airport)		smoke detector, fire extinguisher	No fire drill was conducted.
N/A	N/A	N/A	Alumni Hall (1131 N. Algona St.)	N/A	fire extinguishers	No fire drill was conducted. Building is only open when having service.
09/21/2011	11-09-0782	1219	Blades Hall (1171 N. Algona St.)	Wed.	fire alarm panel, smoke detector, horns, fire extinguisher	All evacuated within the two minutes.
09/28/2011	11-09-0782	1145	Chlapaty Wellness Center (150 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	Exterior strobe light did not function. All evacuated within the two minutes.
			Daycare Center (1001 McCormick St.)		fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher	No fire drill was conducted by security staff only by Daycare staff.
09/21/2011	11-09-0782	1301	Dunlap Technology Building (1250 McCormick St.)	Wed.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All evacuated within the two minutes.

09/28/2011	11-09-0782	1057	Goldthorp Science Hall (1150 N. Algona St.)	Wed.	fire alarm panel,battery back-up,smoke detector,heat detector,stroke lights,horns,fire extinguisher,fire door,sprinkler system-water	All evacuated within the two minutes.
N/A	N/A	N/A	Heating Plant (755 Auburn Street)	N/A	fire extinguishers	No fire drill was conducted. Building is only staffed when maintenance work is being done on systems.
09/21/2011	11-09-0782	1208	Hub	Wed.	fire extinguishers	Staff could not hear the sounder. All evacuated within the two minutes.
			Maintenance Bldg. (125 McCormick Street Extension)		fire extinguishers	No fire drill was conducted.
09/28/2011	11-09-0782	1111	McCormick/Stoltz Gym (1050 McCormick St.)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All evacuated within the two minutes.
09/28/2011	11-09-0782	1158	Mercer/Birmingham Hall (205 McCormick Street Extension)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors	All evacuated within the two minutes.
09/28/2011	11-09-0782	1126	Myers Building MTAC (455 North Algona)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	Staff of the ASC complained that they could not hear the alarm inside their area. All evacuated within the two minutes.
09/28/2011	11-09-0782	1326	Myers Library (2105 Grace Street)	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.
09/28/2011	11-09-0782	1415	Peters Commons (1100 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	No horns inside the Snack Bar area. All evacuated within the two minutes.
09/21/2011	11-09-0782	1251	Severance Hall (1000 N. Algona St.)	Wed.	fire alarm panel, strobe lights, horns, fire extinguishers	The students in the back classrooms and lounge area are not able to hear any of the alarm bells in the event of a fire emergency. All evacuated within the two minutes.
09/21/2011	11-09-0782	1319	Smith Hall (2205 Grace Street)	Wed.	horns, fire extinguishers	Room 200 could not clearly hear the alarm. All evacuated within the two minutes.
09/21/2011	11-09-0782	1208	Van Vliet Hall (1025 N. Algona St.)	Wed.	Fire alarm panel, horns, fire extinguishers	All evacuated within the two minutes.

2010 Fire Drills

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
---------------	-------------	---------------	-----------	-------------	-----------------------------------	---------------

04/12/2010	10-04-0433	939	Goldthorp Science Center	Mon.	fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system(water)	All evacuated within the two minutes.
04/12/2010	10-04-0433	954	Dunlap Technology	Mon.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All evacuated within the two minutes.
04/12/2010	10-04-0433	1008	McCormick/ Stoltz Gym	Mon.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	1 Coach failed the evacuate. All others evacuated within the two minutes.
04/12/2010	10-04-0433	1022	Smith Hall	Mon.	horns, fire extinguishers	Room 200 could not clearly hear the alarm. All others evacuated within the two minutes.
04/12/2010	10-04-0433	1034	Van Vliet Hall	Mon.	Fire alarm panel, horns, fire extinguishers	All evacuated within the two minutes.
04/12/2010	10-04-0431	1946	Park Village 2475	Mon.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
04/13/2010	10-04-0438	1033	Blades Hall	Tue.	fire alarm panel, smoke detector, horns, fire extinguisher	All evacuated within the two minutes.
04/16/2010	10-04-0459	936	Peters Commons	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All evacuated within the two minutes.
04/22/2010	10-04-0486	1815	Park Village 2465	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. Emergency lighting on the 3rd floor did not work. All evacuated within the two minutes.
04/22/2010	10-04-0486	1823	Park Village 2545	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.
04/22/2010	10-04-0486	1823	Park Village 2475	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. Emergency lighting on the 3rd floor did not work. All evacuated within the two minutes.
04/22/2010	10-04-0486	1834	Park Village 2535	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.

04/22/2010	10-04-0486	1845	Park Village 2525	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	The audible alarm can barely be heard on the 3rd floor, it can not be heard in the rooms, or in the common area inside the suites. All evacuated within the two minutes.
04/22/2010	10-04-0486	1845	Park Village 2455	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	When inside the apartments the audible was muffled. If using the bathroom the audible would not be heard. The room furthest from the hallway audible could barely be heard. All evacuated within the two minutes.
04/29/2010	10-04-0529	1143	Severance Hall	Thur.	fire alarm panel, strobe lights, horns, fire extinguishers	The students in the back classrooms are not able to hear any of the alarm bells in the event of a fire emergency. All others evacuated within two minutes
04/29/2010	10-04-0529	1153	Myers Building	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	The strobe in the men's restroom on the 1st floor near the business office did not work. All evacuated within the two minutes.
04/29/2010	10-04-0529	1213	Chlapaty Wellness Center	Thur.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.
04/29/2010	10-04-0533	1804	Aitchison Hall	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
04/29/2010	10-04-0533	1831	Donnell Hall	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
04/29/2010	10-04-0533	1844	Cassat Hall	Thur.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
09/27/2010	10-09-1238	1810	Cassat Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All evacuated within the two minutes.
09/27/2010	10-09-1238	1837	Donnell Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(1) student failed to leave within two minutes. All other students evacuated within the two minutes.
09/28/2010	10-09-1246	1755	Aitchison Hall	Tue.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	Audible were not functioning in the following rooms: 111, 211 201 202 207. All evacuated within the two minutes.
09/28/2010	10-09-1246	1828	Park Village 2475	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.

09/28/2010	10-09-1246	1836	Park Village 2465	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
09/29/2010	10-09-1251	1747	Potterveld A	Wed.	smoke detector, fire extinguisher, fire doors	All evacuated within the two minutes.
09/29/2010	10-09-1251	1751	Potterveld B	Wed.	smoke detector, fire extinguisher, fire doors	All evacuated within the two minutes.
09/29/2010	10-09-1251	1815	Potterveld C	Wed.	smoke detector, fire extinguisher, fire doors	All evacuated within the two minutes.
09/30/2010	10-09-1255	1806	Park Village 2455	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
09/30/2010	10-09-1255	1818	Park Village 2545	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
09/30/2010	10-09-1255	1823	Park Village 2535	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
09/30/2010	10-09-1255	1829	Park Village 2525	Thur.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All evacuated within the two minutes.
10/08/2010	10-10-1304	936	Smith Hall	Fri.	horns, fire extinguishers	All evacuated within the two minutes.
10/08/2010	10-10-1304	944	Van Vliet Hall	Fri.	Fire alarm panel, horns, fire extinguishers	All evacuated within the two minutes.
10/08/2010	10-10-1304	955	Blades Hall	Fri.	fire alarm panel, smoke detector, horns, fire extinguisher	All evacuated within the two minutes.
10/08/2010	10-10-1304	1005	Severance Hall	Fri.	fire alarm panel, strobe lights, horns, fire extinguishers	All evacuated within the two minutes.
10/19/2010	10-10-1354	1354	Dunlap Technology	Tue.	fire alarm panel, battery back-up, strobe lights, horns, fire extinguisher, sprinkle system(water)	All evacuated within the two minutes.
10/19/2010	10-10-1354	1404	Myers Building	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	(2) staff members failed to evacuate. All others evacuated within the two minutes. One strobe light did not work in the 1st floor men's room.
10/19/2010	10-10-1354	1418	Chlapaty Wellness Center	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	One strobe light did not work in the 3rd floor North end, and one on the South side near the southern glass door. All evacuated within the two minutes.
11/02/2010	10-11-1403	1409	Goldthorp Science Center	Tue.	fire alarm panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire door, sprinkler system(water)	All evacuated within the two minutes.

11/02/2010	10-11-1403	1422	McCormick/ Stoltz Gym	Tue.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, sprinkler system(water)	All evacuated within the two minutes.
11/02/2010	10-11-1403	1440	Peters Commons	Tue.	fire alarm panel, strobe lights, horns, fire extinguishers	All evacuated within the two minutes.
11/03/2010	10-11-1406	1432	Myers Library	Wed.	fire alarm panel, battery back-up, monitor internally, smoke detector, heat detector, strobe lights, horns, fire extinguisher, fire doors, sprinkler system(water)	All evacuated within the two minutes.

2009 Fire Drills

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
03/17/2009	09-03-0325	2100	Cassat Hall	Tue.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(1) student failed to leave within two minutes
03/17/2010	09-03-0325	2100	Donnell Hall	Tue.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
03/18/2009	09-03-0326	2000	Park Village 2455	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	(4) students failed to leave within two minutes
03/18/2009		2130	Park Village 2465	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
03/18/2009	09-03-0326	2000	Park Village 2475	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	(2) students failed to leave within two minutes
03/19/2009		2130	Park Village 2525	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
03/19/2009		2130	Park Village 2535	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes

03/19/2009		2130	Park Village 2545	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
10/12/2009	09-10-1039	1958	Cassat Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(2) students failed to leave within two minutes
10/12/2009	09-10-1039	1958	Aitchison Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
10/13/2009	09-10-1048	1938	Donnell Hall	Tue.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(1) student failed to leave within two minutes
10/13/2009	09-10-1048	1948	Park Village 2455	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	(2) students failed to leave within two minutes
10/13/2009	09-10-1048	1948	Park Village 2475	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	(2) students failed to leave within two minutes

2008 Fire Drills

Date of Drill	Case Number	Time of Drill	Hall Name	Day of Week	Description of Fire Safety System	Brief Summary
03/17/2008	09-03-0325	2100	Cassat Hall	Tue	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(1) student failed to leave within two minutes
03/17/2008	09-03-0325	2100	Donnell Hall	Tue	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
04/21/2008	08-04-0435	1953	Cassat Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(2) students failed to leave within two minutes
04/21/2008	08-04-0435	2012	Aitchison Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
04/21/2008	08-04-0435	2034	Donnell Hall	Mon.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	(3) students failed to leave within two minutes

04/22/2008	08-04-0443	2024	Park Village 2465	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
04/22/2008	08-04-0443	2024	Park Village 2475	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
04/22/2008	08-04-0443	2038	Park Village 2455	Tue.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
04/23/2008		2030	Park Village 2525	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
04/23/2008		2030	Park Village 2535	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
04/23/2008		2045	Park Village 2545	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
09/11/2008	08-09-1008	2128	Cassat Hall	Thu.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
09/11/2008	08-09-1011	2130	Donnell Hall	Thu.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes
09/24/2008		2045	Park Village 2525	Wed.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
09/25/2008	08-09-1068	2030	Park Village 2455	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	(2) students failed to leave within two minutes
09/25/2008	08-09-1068	2100	Aitchison Hall	Thu.	fire panel, battery back-up, smoke detector, heat detector, strobe lights, horns, fire extinguishers, fire doors	All students evacuated within two minutes

09/25/2008		2100	Park Village 2535	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
09/25/2008		2120	Park Village 2545	Thu.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
09/26/2008	08-09-1075	2055	Park Village 2475	Fri.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes
09/26/2008	08-09-1075	2120	Park Village 2465	Fri.	fire panel, battery back-up, monitor(external vendor), monitor(internal), smoke detector, heat detector, strobe lights, horns, fire extinguishers, sprinkler system(water)	All students evacuated within two minutes